

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 08 Dec 2022

## **Preliminary Advice**

Vehicle No	: SMK4244B	Accident Date	: 24/11/2022
Make	: MERCEDES-BENZ GLA200	Policy No.	: SP2001491346
Assignment Date	: 06/12/2022	Excess	: S\$800.00
Date of Inspection	:	Est. Duration of Repair	: 5 DAYS
Inspection At	: AUTO INSURE PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,473.00
Revised Amount	:S\$	4,051.50
Check Items (Estimated)	:S\$	1,465.00
Total	:S\$	5,516.50

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	38,016.00
Salvage Value	:S\$	
Margin for Repair	:S\$	76,984.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part repair. According to the repairer, there are no second-hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.