



Case Details

Case Reference Number : TAX/12/22/2014
Type of Repair : Accident Repair
Vehicle Registration Number : SHB916C

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19987-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 06/12/2022 03:00 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL-BODY SI OTR - RH	1	1,434.89	1,434.89	10.00	1,291.40	Replace	1	0	Repair	X Repair
Standard	Main			STICKER ELECTRIC (LOGO	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ abc
Standard	Main			PANEL ASM-RR END	1	708.66	708.66	10.00	637.79	Replace	0	0	Check	?
Standard	Main			LINER ASM-RR W/H PNL - RH	1	85.48	85.48	10.00	76.93	Replace	1	76.93	Replace	/ Re
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	682.63	Replace	/ Re
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	/ Cnt
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	1	42.68	Replace	/ CRA
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-RH	1	29.85	29.85	10.00	26.87	Replace	0	0	Check	?
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - RH	1	46.08	46.08	10.00	41.47	Replace	1	41.47	Replace	/ Cnt
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG	1	12.79	12.79	10.00	11.51	Replace	0	0	Check	?
Standard	Main			BOLT/SCREW-FRT W/H LNR RET	10	0.52	5.20	10.00	4.68	Replace	10	4.68	Replace	/ acc
Standard	Main			BAR ASM-RR BPR IMP	1	339.78	339.78	10.00	305.78	Replace	1	305.78	Replace	/ BT
Standard	Main			COVER-RR TOW HOOK OPG	1	6.76	6.76	10.00	6.08	Replace	0	0	Not Give	X NN
Standard	Main			LAMP ASM-TAIL(BODY SI) - RH	1	764.09	764.09	10.00	687.68	Replace	0	0	Check	?
Total Spare Part Cost									7,150.17	Surveyor Total		1,553.54		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									7,150.17	Final Sur Total		1,553.54		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			LAMP ASM-RR FOG - RH	1	189.07	189.07	10.00	170.16	Replace	1	170.16	Replace	✓ -CHA
Standard	Main			STRUT-RR SUSP	1	322.61	322.61	10.00	290.35	Replace	0	0	Not Give	✓ X an
Standard	Main			BEARING ASM-RR WHL	1	335.40	335.40	10.00	301.86	Replace	0	0	Check	✓ ?
Standard	Main			BEAM ASM-RR SUSP EQLZR	1	1,649.54	1,649.54	10.00	1,484.59	Replace	0	0	Not Give	✓ X an
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	10.00	175.50	Replace	0	0	Check	✓ ?
Standard	Main			WHEEL	1	618.07	618.07	10.00	556.26	Replace	1	0	Repair	✓ X Repri
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X an
Total Spare Part Cost									7,150.17	Surveyor Total 1,553.54				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									7,150.17	Final Sur Total 1,553.54				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	1,200.00	500	
Total:			1,200.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
2	Main	TO RESPRAY REAR PANEL	230.00	0	X an
3	Main	TO RESPRAY REAR FENDER RH	428.00	220	
4	Main	TO RESPRAY RIM	230.00	100	
Total:			1,316.00	540.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	112.00	0	REQ INVOICE
2	Main	TO WASH AND VACUUM	60.00	0	X an
Total:			1,682.00	430.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	X an
5	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
7	Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	0	X
8	Main	TO REMOVE AND REFIT REAR CROSSMEMBER	250.00	0	X } m
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	X
10	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
11	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			1,682.00	430.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,150.17	1,553.54
Total Labour Cost	1,200.00	500.00
Total Spray Painting	1,316.00	540.00
Other	1,682.00	430.00
Overall Total	11,348.17	3,023.54
Lump Sum Repair Option		
Lump Sum Total	0.00	3,023.54
Surveyor Approved Amount		3,023.54
No of Repair Days*	10	
Remarks	-	
Surveyor Name		
Signature		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey must provide PROOF OF REPAIR ITEM. PLEASE CALL SURVEYOR quociang (LKK) & Email quociang@lkkauto.com HP:82880282
- No illegal modification allowed
- Supplemental work must be approved and signed by LKK Auto Consultants

Acknowledged by: _____

Signature: _____

Date: _____

Save Clear