

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: #02-146 Singapore 608586
Date: Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Automotive Repair Centre Pte Ltd

Estimate

ESTIMATE NO. : EST2212-665-TG

DATE : 8-Dec-2022

VEHICLE REG. NO. : SMQ3817Y

VEHICLE MAKE : HONDA / JAZZ 1.5 VTIR CVT ABS D/AIRB

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul - 4p 90010068
5 days - L/S
08/12/22 @ 1220
Rasul after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de</i>	1	\$ 529.90	\$ 529.90
2	Rear Bumper Side Retainer LH <i>XAN</i>	1	\$ 24.90	\$ 24.90
3	Rear Bumper Side Retainer RH <i>XAN</i>	1	\$ 24.90	\$ 24.90
4	Rear Tailgate <i>bt</i>	1	\$ 980.10	\$ 980.10
5	Rear Tailgate Lock <i>XAN</i>	1	\$ 187.20	\$ 187.20
6	Rear Tailgate Weatherstrip <i>rec</i>	1	\$ 112.30	\$ 112.30
7	Rear Tailgate Logo (Hybrid) <i>rec</i>	1	\$ 85.60	\$ 85.60
8	Rear Tailgate Logo (Fit) <i>rec</i>	1	\$ 55.70	\$ 55.70
9	Rear Tailgate Glass Moulding <i>rec</i>	1	\$ 126.20	\$ 126.20
10	Rear End Panel <i>repair</i>	1	\$ 449.60	\$ 449.60
11	Rear End Panel Top Garnish <i>XAN</i>	1	\$ 150.60	\$ 150.60
12	Rear Antenna <i>XAN</i>	1	\$ 100.00	\$ 100.00
Total Spare Parts				\$ 2,827.00
SPECIAL NETT				
13	Reverse Sensor <i>XAN</i>	1	\$ 280.00	\$ 280.00
14	Rear Bumper Clips <i>rec</i>	10	\$ 4.00	\$ 40.00
15	Rear Windscreen Sealant <i>rec</i>	1	\$ 50.00	\$ 50.00
Total Special Nett				\$ 370.00
LABOUR				
16	Remove, Refit and Align Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00
17	Spray Paint (Rear Bumper, Rear Bumper Lwr, Tailgate and End Panel)	1	\$ 1,000.00	\$ 1,000.00
18	Transfer Tailgate Fitting, Window Mechanism to New Tailgate	1	\$ 80.00	\$ 80.00
19	Remove and Replace Rear Windscreen	1	\$ 150.00	\$ 150.00
20	Remove and Refit Rear Bumper Sensor	1	\$ 80.00	\$ 80.00
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
22	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,440.00
Amount Before Excess				\$ 5,637.00
Add GST @ 7%				\$ 394.59
Total Amount Payable				\$ 6,031.59

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

1889.80
208
1511.84

200? X
30
30 360

500

600

60

120

40

80

XAN

1511.84

60.00

1360.00

2931.84

208

2345.77

43 - \$2350

5 days