



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22012206/Uvy3e2	
			Date: 04/01/2023	
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBW 6163D	Veh. Inspected	SMS 2229R	
Policy No.	P10155807R03	Coverage (\$)	0.00	
Claim No.	C10019058/JL	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	06/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE 2.5 (A)	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	AGH300028399	Colour	GREY	
Odometer	92506 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40Z R20	MICHELIN	6 mm	
L/H Front Tyre	255/40Z R20	MICHELIN	6 mm	
R/H Rear Tyre	255/40Z R20	MICHELIN	6 mm	
L/H Rear Tyre	255/40Z R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2022	Inspection Date	12/12/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	