



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7054Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE DOOR R/H	TO REPAIR SEE LABOUR	1,168.00	-
1	SIDE DOOR HINGE R/H	NOT NECESSARY	60.00	-
1	SIDE DOOR LOCK R/H	NOT NECESSARY	280.00	-
1	SIDE DOOR CATCH R/H	NOT NECESSARY	235.00	-
1	SIDE DOOR OUTER HANDLE LEVER R/H	NOT NECESSARY	120.00	-
1	SIDE DOOR SIGNAL LIGHT R/H	NOT NECESSARY	77.60	-
1	WHEEL ARCH PANEL R/H	GRAZED	435.00	295.10
1	COOLANT TANK	DEFORMED	135.00	135.00
1	FUEL TANK	TO REPAIR SEE LABOUR	780.00	-
1	CANOPY CANVASS	NOT NECESSARY	326.00	-
1	SIDE PANEL	TO REPAIR SEE LABOUR	786.00	-
1	CARRIER SIDE GATE R/H	TO REPAIR SEE LABOUR	1,865.00	-
1	CARRIER SIDE GATE SAFETY FENCE R/H	TO REPAIR SEE LABOUR	600.00	-
1	CARRIER BARRIER PANEL R/H	TO REPAIR SEE LABOUR	655.00	-
	LESS 25% DISCOUNT		-1,880.65	-107.53
			5,641.95	322.57
	<u>SPECIAL NETT ITEMS</u>			
1	SIDE TAILGATE CHECKER PLATE (SN)	NOT NECESSARY	600.00	-
1	CARRIER SIDE GATE STOPPER (SN)	TORN	40.00	40.00
			640.00	40.00
	<u>LABOUR</u>			
	TO CHECK WIRING .	NOT NECESSARY	80.00	-
	SPRAY RUST PROOFING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING.INCLUSIVE OF THE REPAIR OF SIDE DOOR R/H ,FUEL TANK,SIDE PANEL,CARRIER SIDE GATE R/H ,CARRIER SIDE GATE SAFETY FENCE R/H AND CARRIER BARRIER PANEL R/H.		2,000.00	600.00

Report Ref No. CS/AGI22012209/Uwy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING.		1,800.00	300.00
			4,000.00	900.00
GRAND TOTAL			10,281.95	1,262.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/AGI22012209/Uwy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.