

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 765761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2002751593-01	Date of Loss:	30/11/2022
Vehicle Reg. No.:	SLF8922M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CALEB NG WEI CHUEN		
Driver:	CALEB NG WEI CHUEN		

Make/Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Vehicle Reg. Date:	15/09/2016
Vehicle Colour:	SILVER		
Engine No:	G4FGGU219177	Chassis No:	KMHD841CMHU238620
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO
0

*Not Authorized
1-B.1, 1/1 Page 8
Recovery After Repair*

Description of Accident/Loss: REFER TO GIA REPORT ATTACHED.

Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS	Amount
Parts	1,843.60
Miscellaneous Items	0.00
Labour	1,450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,293.60
+ GST 7.00% (S\$)	230.55
Nett Amount (S\$)	3,524.15

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Meritman e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To renew before/after spray painting
- To display damaged part(s) during renewal
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Replacement part(s) must be new/unused and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
Signature: _____
Date: _____

Lump Sum / I.B.I. (S)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Dec 2022)
 Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SLF8922M/06/12/2022 12:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SLF8922M
 05/11/2022

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER			
2	1		*1 PC FRT BUMPER RH RETAINER			
3	1		*6 PCS FRT BUMPER CLIPS @2/PC			
4	1		*1 PC FRT BUMPER RH FOG LAMP			
5	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH			
6	1		*1 PC FRT BUMPER RH DAY RUNNING LAMP			
7	1		*1 PC FRT BUMPER SIDE TOP RETAINER RH			
8	1		*14 PCS FRT BUMPER SIDE TOP RETAINER RIVETS @2/PC			
9	1		*1 PC FRT BUMPER LOWER REINFORCEMENT			
10	1		*1 PC FRT BUMPER SPONGE			
11	1		*1 PC FRT BUMPER REINFORCEMENT			
12	1		*1 PC RH HEADLAMP			
13	1		*1 PC RH HEADLAMP LOWER BRACKET			
14	1		*1 PC FRT RH FENDER			
15	1		*1 PC FRT RH FENDER DUST COVER			
16	1		*6 PCS FRT RH FENDER DUST COVER CLIPS @2/PC			
17	1		*1 PC FRT SUPPORT TOP COVER			

F=Franchise part

Sub Total (\$\$) 1,676.00
 + Margin on L,N Items 10.00% (\$\$) 167.60
 Total Parts (\$\$) 1,843.60

Cheng Hoe Motor Pte Ltd/SLF8922M/06/12/2022 12:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	TOWING	New	50.00
2	REMOVE DAMAGED FRT BUMPER,RH FENDER,BUMPER & ATTACHMENTS,PANEL BEAT & REPAIR RH FENDER APRON,INNER PANEL,BRACKETS	New	600.00
3	SPRAY PAINTING FRT BUMPER,FRT RH FENDER,FRT RH DOOR,FRT INNER PANEL,BONNET AND ALL AFFECTED AREAS	New	800.00
Gross Labour Cost (\$\$)			1,450.00

Cheng Hoe Motor Pte Ltd/SLF8922M/06/12/2022 12:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Report Format

Lump Sum / L.B.I: (\$