

Our Job Ref No : 305538587

Date : 10/12/22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. : SHC 24X

04.12.2022


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- GBL1218X
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost** \$0.00
- (c) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% \$3,850.00
- Final Lumpsum Repair cost** \$3,850.00

3. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 15/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC24X

Make : HYUNDAI

Model : IONIQ(G3)

Date: 05/12/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR DOOR OUTER MOULDING RH			\$ 125.30	DEF
1	REAR DOOR OUTER HANDLE RH			\$ 108.40	SCR
1	REAR FENDER RH			\$ 1,768.30	DD
1	REAR FENDER SHIELD RH			\$ 173.60	X SVC
1	REAR DOOR RH			\$ 2,147.90	DD
	SUB TOTAL		4,149.90	\$ 4,323.50	
	LESS 20%			\$ 864.70	
	DISCOUNTED TOTAL		3,319.92	\$ 3,458.80	
	REAR DOOR COMFORTDELGRO APP STICKER RH			\$ 80.00	NEL
				\$ 80.00	
	Labour Charge				
	PANEL BEATING			\$ 1,050.00	700
	SPRAY PAINTING CHARGE			\$ 800.00	650
	TRANSFER OF DOOR			\$ 120.00	50
	TUFF KOTE			\$ 60.00	40
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR			\$ 120.00	XNN
	TOTAL LABOUR		4839.92	\$ 2,150.00	
	ESTIMATE TOTAL			\$ 5,688.80	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKIC

5/12/2022 1610

LIS

3 DAYS

CHECK ITEM PHOTO

(AFTER REPAIR PHOTO)

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**