COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Make

Vehicle No.: SHC24X : HYUNDAI

Model : IONIQ(G3)

Date: 05/12/2022 Insurance: INCOME MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount		
1	REAR DOOR OUTER MOULDING RH			\$	125.30	/DEF
1	REAR DOOR OUTER HANDLE RH			\$	108.40	15CR
1	REAR FENDER RH			\$	1,768.30	100
1	REAR FENDER SHIELD RH			\$	173.60	?
1	REAR DOOR RH			\$	2,147.90	/DD
	SUB TOTAL			\$	4,323.50	
	LESS 20%			\$	864.70	
	DISCOUNTED TOTAL			\$	3,458.80	
	REAR DOOR COMFORTDELGRO APP STICKER RH			\$	80.00	-NEC
				\$	80.00	
L	abour Charge					
F	PANEL BEATING			\$	1,050.00	700
s	PRAY PAINTING CHARGE			\$	800.00	650
Т Т	RANSFER OF DOOR			\$	120.00	50
Т	UFF KOTE			\$	60.00	40
R	EMOVE/ REFIX UPHOLSTERY & CUSHION RR			\$	120.00	XNN
	TOTAL LABOUR			\$	2,150.00]
	ESTIMATE TOTAL			\$	5,688.80	_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK 5/12/2022 16/0 115 3 Days CHECK ITEM PHOTO, MITTEL REPOR PHOTOS

LKK. Auto Consultants hence notify

- the Repairer of the following:
- · resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: