



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8212K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TRUNK COVER	TO REPAIR SEE LABOUR	1,303.29	-
1	REAR TRUNK OUTER GARNISH	TO REPAIR SEE LABOUR	1,054.71	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	81.43	81.43
1	REAR BUMPER -G4A	CRACKED	551.89	551.89
1	REAR BUMPER REINFORCEMENT	BENT	378.32	378.32
1	REAR BUMPER LOWER COVER -BLACK	CRACKED	654.96	654.96
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	55.00	-
1	REAR BUMPER SIDE BRKT RH	SERVICEABLE	112.70	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	BUCKLED	82.70	82.70
1	REAR W/SCREEN WITH MOULDING	NOT NECESSARY	1,758.70	-
1	REAR LOWER W/SCREEN (BLACK)	NOT NECESSARY	805.80	-
	LESS 25% DISCOUNT		-1,746.45	-473.90
			5,239.33	1,421.68
<b><u>NETT ITEMS</u></b>				
1	REVERSE SENSOR (N)	SERVICEABLE	135.70	-
1	REAR TRUNK COMFORTDELGRO (N)	NECESSARY	30.00	30.00
1	REAR TRUNK 65521111 (N)	NECESSARY	30.00	30.00
1	REAR TRUNK APPS (N)	NECESSARY	40.00	40.00
2	WINDSCREEN SEALANT @\$46.00 (N)	NOT NECESSARY	92.00	-
1	REAR NO.PLATE WITH TRIM COVER (N)	DEFORMED	55.00	55.00
	LESS 10% DISCOUNT		-38.27	-15.50
			344.43	139.50
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TRUNK COVER AND REAR TRUNK OUTER GARNISH .		800.00	700.00

Report Ref No. NS/INC22012232/Nnp3q2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		900.00	650.00
	WIRING CHARGE.	NOT NECESSARY	40.00	-
	TUFF KOTE.		100.00	40.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	30.00
	R/I REAR WINDSCREEN GLASSES.	NOT NECESSARY	240.00	-
			2,200.00	1,420.00
<b>GRAND TOTAL</b>			<b>7,783.76</b>	<b>2,981.18</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,981.18</b>

Report Ref No. NS/INC22012232/Nnp3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.