

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Arthur
7/12/22
1/546000/
2 days.

VEHICLE No: SJD 1319K

1PC	FRONT BUMPER	Dis/To-1	1636.54	\$2,215.32	✓
1PC	FRONT BUMPER BEAM	11		\$845.10	X
1PC	FRONT BUMPER SIDE RETAINER N/S	11		\$105.00	✓
2PCS	FRONT BUMPER PDC SENSORS @\$190.00	11		\$380.00	X
1SET	FRONT BUMPER CLIPS & RIVET	11		\$60.00	✓
1PC	FRONT BUMPER LOGO	11		\$85.00	X
1PC	FRONT BUMPER SPONGE	11		\$162.00	X
1PC	FRONT HEADLAMP N/S	11	3366.07	\$6,500.00	✓
1PC	FRONT SUPPORT PANEL	11		\$845.11	X
1PC	FRONT FENDER N/S	3065.00		\$1,018.00	✓
1PC	FRONT FENDER INNER SHIELD N/S	11	269.80	\$381.00	✓
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	11		\$60.00	✓
1PC	FRONT SPORT RIM 17 INCH	11	920	\$1,500.00	✓
1PC	FRONT LOWER ARM N/S	11		\$611.20	X
1PC	FRONT KNUCKLE ARM N/S	11		\$1,006.00	X
1PC	FRONT WHEEL HUB BEARING N/S	11	102	\$650.00	X
				\$16,423.73	

TO CHECK WIRING
TO DISMANTLE & REPLACED FRT PDC SENSOR
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REPLACED FRT UNDER CARRIAGE
TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 40
\$80.00 30
\$120.00 60
\$180.00 X
\$180.00 X
\$880.00 300
\$1,200.00 400
TOTAL \$19,193.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-7434-41
102
6691.86
850
7541.86