

Think One Autocare Pte Ltd
No.60 Jalan Lam Huat #02-32 Carros Centre
Singapore 737869

ESTIMATED

VEHICLE NO: PC2963C YUTONG ZK6126

DATE 05.12.2022

No	Qty	PARTICULAR	AMOUNT S\$
1	1	FRONT CORNER PANEL LH	5,843.00 ✓
2	1	FRONT PASSENGER DOOR <i>pkj</i>	3,522.00 ✓
3	1	FRONT HEADLAMP LH ASSY	3,588.00 X
4	1	HEADLAMP COVER LH	285.00
5	1	FRONT BUMPER	2,855.00 X
6	1	SIDE REFLECTOR	56.00 ✓
			\$ 16,149.00
Less 10%			\$ 1,614.90
			\$ 14,534.10

No	SPECAIL NETT	AMOUNT S\$
1	3 FRONT WINDSCREEN SEALANT	250.00 <i>1200</i>
2	1 FRONT WINDSCREEN INNER SEAL	150.00 <i>600</i>
		\$ 400.00

No	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	3,800.00 <i>2000</i>
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,800.00 <i>800</i>
3	To remove,refix dashboard with all necessary components/attachments	250.00 X
4	To remove,refix front windscreen glass and water test	800.00 <i>300</i>
5	To conduct headlamp alignment	50.00 <i>20</i>
		\$ 6,700.00

*NOT Author
C/Pg 8
Return After Paid
5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are on "without Prejudice" basis
- No illegal modifications to be allowed
- Supplemental (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Rep. over

Signature:

Date:

Menara

96910663

Menara Keng @ LKK Auto.com