

ASS. REC. BY:

REF:

A15/22012236/kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKQ 1413R Yr Regn: 08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Car B1

1/2

3572.44 Cash

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Fuel

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN MOH CHYE STEVEN
 352 HOUGANG AVE 7
 #11-735
 SINGAPORE 530352
 TEL: 81239008
 ATTN:

Estimate No: MC1903168
 Date: 02 Dec 2022
 Policy No: 5128234010
 Veh Reg No: SKQ1413R
 Make/Model: HONDA SHUTTLE 1.5G
 CVT

Your Ref No: SKQ1413R
 Claim Type: Third Party
 Accident Date: 30/11/2022
 TP Veh Reg No: SLG9530Z

*Not Authorised
 Repair B4 paint
 4 days*

Estimate Repair Cost to Vehicle No :SKQ1413R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN MLDG	1 PC	149.20	—
2 TAILGATE	1 PC	1,193.40	✓
3 TAILGATE EMBLEM	1 PC	38.40	✓
4 TAILGATE LAMP LH & RH	2 PC	680.40	X
5 TAILGATE NO PLATE GARNISH W CHROME MLDG	1 PC	410.20	X
6 TAILGATE SHUTTLE LOGO	1 PC	59.40	—
7 TAILGATE LOWER INNER TRIM	1 PC	220.80	X
8 TAILGATE RUBBER	1 PC	168.20	X
9 TAILGATE LOCK	1 PC	228.40	X
10 TAILGATE LOCK CATCH	1 PC	36.40	X
11 TAILAMP LH & RH	2 PC	1,040.80	X
12 REAR BUMPER	1 PC	1,180.20	✓
13 REAR BUMPER CLIPS	8 PC	28.00	✓
14 REAR BUMPER CHROME MLDG	1 PC	148.20	✓
15 REAR BUMPER REFLECTOR LH & RH	2 PC	118.80	X
16 REAR BUMPER SPONGE LH & RH	2 PC	196.40	X
17 REAR BUMPER SIDE RETAINER LH & RH	2 PC	58.80	X
18 REAR END PANEL	1 PC	560.80	X
19 REAR END PANEL GARNISH	1 PC	155.40	X
20 REAR BUZZER	1 PC	80.10	X
21 REAR KEY ANTENNA	1 PC	58.20	X
22 REAR FENDER COWLING CLIPS	16 PC	56.00	X
		6,866.50	
	Less 20%	1,373.30	5,493.20
Special Nett			
23 INNER SEAL	1 PC	20.00	✓
24 WINDSCREEN SEALANT	1 PC	40.00	✓
25 NUMBER PLATE	1 PC	35.00	X
26 REVERSE SENSOR	1 SET	200.00	✓
		295.00	295.00
LABOUR			
27 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	156
28 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓

Zila
 Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN MOH CHYE STEVEN
352 HOUGANG AVE 7
#11-735
SINGAPORE 530352
TEL: 81239008
ATTN:

Estimate No: MC1903168
Date: 02 Dec 2022
Policy No: 5128234010
Veh Reg No: SKQ1413R
Make/Model: HONDA SHUTTLE 1.5G
CVT

Your Ref No: SKQ1413R
Claim Type: Third Party
Accident Date: 30/11/2022
TP Veh Reg No: SLG9530Z

Estimate Repair Cost to Vehicle No :SKQ1413R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00 ✓	
30 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00 501	
31 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00 301	
32 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00 4001	
33 TO SPRAY TAILGATE,REAR BUMPER,RR END PANEL, SPARE TYRE PANEL.	1 PC	800.00 4001	
		1,940.00	1,940.00
		Total	S\$ 7,728.20
		Add GST @ 7%	540.97
		Total Amount Payable	S\$ 8,269.17

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED SIXTY NINE AND CENTS SEVENTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE