

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22012238/Tvy3m4
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/05/2023
			Code	AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 421B	Veh. Inspected	SMQ 8698R
	Policy No.	P10783361R00	Coverage (\$)	0.00
	Claim No.	C10019079 /JL	Excess (\$)	0.00
	Assign From	FRAULEINE KHOO	Assign Date	07/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GK33423626	Colour	WHITE
	Odometer	48547 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195/55R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/55R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/55R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/55R15	YOKOHAMA	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	03/12/2022	Inspection Date	15/12/2022
	Survey held at	CARSMITH PTE LTD		
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a.	a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: