

ASS. REC. BY: TaughtREF: CS/AG/22012238/TVY3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$80k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMQ8698R Yr Regn: 2019 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1317Colour: white A/C: Insured / Std / NI / NASp. Reading: 48547 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 33423626

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 55R15R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 15/12/22 @ 315mSurvey held at Carsmith

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / C. _____

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: SMQ8698R

MAKE & MODEL: HONDA FIT

DOA: 03.12.2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
END PANEL	1	\$ 755.00	RY
BOOT LID	1	\$ 1,750.00	RV
REAR BUMPER	1	\$ 1,256.40	del ✓ 495.90
REAR BUMPER RETAINER LH	1	\$ 120.20	X nn
REAR BUMPER RETAINER RH	1	\$ 120.20	X nn
REAR BUMPER LOWER GRILLE	1	\$ 565.80	cut ✓ 146.90

\$ 4,567.60

LESS 25% \$ 1,141.90

SUB TOTAL \$ 3,425.70

642.80

20% - 514.24

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE W/GARNISH	1	\$ 90.00	X nn
REVERSE SENSOR	1 SET	\$ 480.00	200 n/w ✓
REAR BUMPER CLIP	1 SET	\$ 50.00	30 n/w ✓
SUB TOTAL		\$ 620.00	

230

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	X nn
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	1	\$ 150.00	60
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 800.00	500
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	500
APPLY ANTI-RUST ON AFFECTED AREAS	1	\$ 100.00	30

1120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

6-11-2022 by Repairer

SUB TOTAL \$ 2,070.00

GRAND TOTAL \$ 6,115.70

L/S Repairing after repair

514.24

230

1120

1864.24

4158/500

03 days