

## COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

DATE: 06.12.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHA3319L

INSURANCE: CHINA TAIPING CP/PMVA: LIM T S

LKK-

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Radiator Grille	1		\$ 1,409.10	/CRA
	Front Bumper Cover	1		\$ 481.10	/CRA
	Front Bumper Lower Grille	1		\$ 285.10	/CRK
	Front Bumper Centre Upper Moulding	1		\$ 368.50	/CRK
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	/NEL
	HeadLamp RH	1		\$ 2,110.30	/SCR
	Front Licence Plate Garnish	1		\$ 188.00	/CRK
	<b>SUB TOTAL</b>			\$ 4,864.10	
	<b>LESS 20%</b>			\$ 972.82	
	<b>DISCOUNTED TOTAL</b>			\$ 3,891.28	
	<b>Frnt No.Plates W/Trim Cover</b>	1		\$ 55.00	/CRA
	<b>NETT TOTAL</b>			\$ 55.00	
	<b>PARTS DISCOUNTED TOTAL</b>			\$ 3,946.28	
	<b>Labour Charge</b>				
	Panel Beating			\$ 400.00	350
	Spray Painting Charge			\$ 300.00	250
	Check Lightings			\$ 40.00	30
	<b>TOTAL LABOUR</b>			\$ 740.00	
	<b>ESTIMATE TOTAL</b>			\$ 4,686.28	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKE  
6/12/2022 1610  
PIP  
2 DAYS  
BEFORE PAINT PHOTOS

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: