

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305538850  
Date : 09.12.2022

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHA3319L

Date of Accident : 05.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBE5731R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (If applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

\$3,650.00

\$3,650.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : NAZ

Tel : 62148398

Date : 14/12/2022

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 06.12.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHA3319L

INSURANCE: CHINA TAIPING CP/PMVA: LIM T S

LKK-

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Radiator Grille	1		\$ 1,409.10	/CRA
	Front Bumper Cover	1		\$ 481.10	/CRA
	Front Bumper Lower Grille	1		\$ 285.10	/CRK
	Front Bumper Centre Upper Moulding	1		\$ 368.50	/CRK
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	/NEI
	HeadLamp RH	1		\$ 2,110.30	/SCR
	Front Licence Plate Garnish	1		\$ 188.00	/CRK
	<b>SUB TOTAL</b>			\$ 4,864.10	4,864.10
	<b>LESS 20%</b>			\$ 972.82	
	<b>DISCOUNTED TOTAL</b>			\$ 3,891.28	
	<b>Frt No. Plate W/Trim Cover</b>	1		\$ 55.00	/CRA
	<b>NETT TOTAL</b>			\$ 55.00	
	<b>PARTS DISCOUNTED TOTAL</b>			\$ 3,946.28	
	<u>Labour Charge</u>				
	Panel Beating			\$ 400.00	350
	Spray Painting Charge			\$ 300.00	250
	Check Lightings			\$ 40.00	30
	<b>TOTAL LABOUR</b>			\$ 740.00	
	<b>ESTIMATE TOTAL</b>			\$ 4,686.28	4,576.28

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK  
6/12/2022 1610  
PIP \$3,650.00 L/Sum  
2 DAYS  
BEFORE PAINT PHOTO

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**