

CS. 111 270122-46 / T9Y3

Veh No: SMH.21456 Yr Regn: 2019 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Stinger 2.0 C.C. 1998

Colour Red A/C: Insured / Std / NI / NA

Sp. Reading 78148 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KN1A E351AMK G05 4257

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: ☒ Inoperative / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: NIL / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R19

R: 1 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /

TOYO / YOKO dr

Front Rear
R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6. mm L/Bal. 6 mm

D.O.A. D.O.I. 14/12/22

Survey held at Flying Hawk

Des. of Damages	Frt	Rear	O/S	N/S	U/C	Roof-top	or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

Date/Time, File Pass to?

☐ : Prel. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

5) $\underline{\hspace{1cm}} S + RS, \underline{\hspace{1cm}} SI$

Photos

1	Others	
---	--------	--

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Formed:

Lump Sum / E.S.: /

FLYING HIGH SPRAY PAINTING

1 Kaki Bukit Avenue 6 #01-29 Autobay @ Kaki Bukit Singapore 417883 Mobile: (65) 9230 3750
Email: fhspainting@gmail.com

Make/Model: KIA STINGER


Engine/Chassis No.: KNAE351AMK6054257 Date of accident:

Damaged area: Rear

Date: 09/02/2023

Claim Type: TP VRN:

SMH2145G



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid	1	\$ 1,269.00	\$ 1,269.00	Rx
2	Bootlid outer garnish	1	\$ 385.00	\$ 385.00	Rx
3	Bootlid logo	1	\$ 62.00	\$ 62.00	na
4	Bootlid "Stinger" emblem	1	\$ 98.00	\$ 98.00	net
5	Bootlid lamp	2	\$ 590.00	\$ 1,180.00	X
6	Bootlid buzzer	1	\$ 269.00	\$ 269.00	X
7	Bootlid inner handle	1	\$ 84.00	\$ 84.00	X
8	Bootlid inner lock	1	\$ 124.00	\$ 124.00	X
9	Bootlid lock sensor	1	\$ 320.00	\$ 320.00	X
10	Bootlid weather strip	1	\$ 147.00	\$ 147.00	X
11	Bootlid striker	1	\$ 85.00	\$ 85.00	X
12	Bootlid inner trimboard	1	\$ 250.00	\$ 250.00	X
13	Taillamp	1	\$ 908.00	\$ 908.00	X
14	Rear bumper	1	\$ 1800.00	\$ 1800.00	de / 830.70
15	Rear bumper retainer	2	RH Xnn \$ 76.00	\$ 152.00	LH de / 76
16	Rear bumper bracket	2	RH Xnn \$ 68.00	\$ 136.00	LH de / 68
17	Rear bumper side cover	2	\$ 287.00	\$ 574.00	Xnn
18	Rear bumper side reflector	2	RH Xnn \$ 87.00	\$ 174.00	LH de / 87
19	Rear bumper reinforcement	1	\$ 294.00	\$ 294.00	ang
20	Rear bumper reinforcement stay	1	\$ 50.00	\$ 50.00	bt
21	Rear bumper cover retainer	2	\$ 52.00	\$ 104.00	Xnn
22	Rear bumper centre lower diffuser	1	\$ 650.00	\$ 650.00	ena / 387.40
23	Rear bumper lower side cowl	2	\$ 198.00	\$ 396.00	Xnn
24	Rear bumper Sponge	1	\$ 235.10	\$ 235.10	Xnn
25	Rear Bumper Tow Cover	1	\$ 43.80	\$ 43.80	de
26	End panel outer	1	\$ 427.00	\$ 427.00	Rx
27	Rear fender inner trim	2	\$ 476.00	\$ 952.00	X
28	Rear licence plate lamp	2	\$ 68.00	\$ 136.00	X
29	Tools holder sponge	1	\$ 197.00	\$ 197.00	X
30	Rear floor panel	1	\$ 794.00	\$ 794.00	X
31	Exhaust assy	1	\$ 578.00	\$ 578.00	bt
32	Exhaust assy mounting	2	\$ 45.00	\$ 90.00	de
33	Exhaust heat shield	1	\$ 187.00	\$ 187.00	X
34	Bootlid hinge	2	\$ 135.00	\$ 270.00	X
35	Bootlid damper	2	\$ 177.00	\$ 354.00	X
36	End panel top garnish	1	\$ 168.00	\$ 168.00	de

37	Rear fender arch garnish	2	\$ 362.00	\$ 724.00
38	Rear bumper lower side bracket	2	\$ 97.00	\$ 194.00
Subtotal				\$ 14,860.90
List discount				10.00%
Total				\$ 13,374.81

X hn
X nn
2832.90
2549.61

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper lower diffuser clips	1 Set	\$ 60.00	\$ 60.00
2	Rear bumper lower side cowlings clips	12	\$ 5.50	\$ 66.00
3	Tailgate outer garnish clips	6	\$ 5.50	\$ 33.00
4	Tailgate lamp clips	6	\$ 5.50	\$ 33.00
5	Tailgate trimboard clips	10	\$ 5.50	\$ 55.00
6	Taillamp clips	6	\$ 5.50	\$ 33.00
7	End panel top garnish clips	6	\$ 5.50	\$ 33.00
8	End panel sealant	1	\$ 100.00	\$ 100.00
9	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
10	Reverse sensor	1	\$ 300.00	\$ 300.00
11	Reverse camera	1	\$ 450.00	\$ 450.00
12	Rear floor panel padding	1	\$ 120.00	\$ 120.00
13	Rear floor panel sealant	1	\$ 100.00	\$ 100.00
14	Tailgate windscreen inner seal	1	\$ 100.00	\$ 100.00
15	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00
16	Rear bumper clips	10	\$ 5.50	\$ 55.00
17	Rear bumper side cover clips	12	\$ 5.50	\$ 66.00
18	Rear bumper lower diffuser	1	\$ 800.00	\$ 800.00
19	Exhaust Tips	2	\$ 175.00	\$ 350.00
20	Rear Exhaust Chrome	2	\$ 200.00	\$ 400.00
Total				\$ 3,309.00

3 Over ✓
X }
X }
X }
X }
X }
X }
X }
X }
X }
2 Wnw ✓
X }
X }
X }
3 Over ✓
X nn
de ✓ 600
bt ✓ 1200
X ✓ 300
1360

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00	600
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	30
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	X m
4	To remove and refit, straighten and readjust exhaust pipe and replace exhaust silencer.	0.5	\$ 100.00	60
5	To upholster to facilitate repair	0.75	\$ 300.00	60
6	To align rear chassis frame and to conduct chassis alignment on Car-O-Liner.	1.5	\$ 300.00	Xan.
7	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00	700
8	To rust proof all affected portions after repair.	0.5	\$ 100.00	1450
Total labour			\$ 3,950.00	
Estimate Grand Total			\$ 20,633.81	

Tanfuk 97495749 2549.61
 14/12/22 1360
 4/5 Resurvey after repair 1450
 05 days 5359.61
 tanfuk (Kuantan) 4/5 4300
 05 days
 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: