



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S2M03XTC

Date: 13<sup>th</sup> Dec 2022

Our Ref: CS3/ASM22003181/Dvp3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Kitty Teo

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKC 2778E**

**INSURED VEHICLE: SHA 2073B**

**ACCIDENT DATE: 04/04/2022**

We thank you for your instruction on 07/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKC 2778E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SKC 2778E and SHA 2073B.
- c) Final Repair Bill of SKC 2778E from M/s Carsmith Pte Ltd.
- d) Colour damaged vehicle photographs of SKC 2778E.

Pre-Repair Inspection Date: 11/04/2022 at M/s Carsmith Pte Ltd, Bartley Biz Centre, 13 Kaki Bukit Road 4 #01-20, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKC 2778E
Make & Model	: B.M.W. Z4 SDrive 35i 3.0L A/T ABS D/AB TC HID
Year of Registration	: 2010
Chassis Number	: WBALM72060E410115
Engine Capacity	: 2979 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.