


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 06.12.2022

Xiao Chen.

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : SND8546C
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 05.12.2022
TIME OF ACCIDENT : 23:25 HRS

RV 31002954

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH <i>Rebed</i>	1	\$ 1,351.00	\$ 1,351.00
2	REAR DOOR LOWER GRANISH RH <i>Rebed</i>	1	\$ 286.00	\$ 286.00
3	REAR DOOR WHEEL ARCH GARNISH RH <i>Rebed</i>	1	\$ 86.00	\$ 86.00
4	REAR DOOR HINGE RH <i>new</i>	2	\$ 55.00	\$ 110.00
5	REAR DOOR INNER LOCK RH <i>new</i>	1	\$ 385.00	\$ 385.00
6	REAR DOOR LOCK CATCHER RH <i>new</i>	1	\$ 25.00	\$ 25.00
7	REAR DOOR INNER TRIM RH <i>new</i>	1	\$ 725.00	\$ 725.00
8	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 145.00	\$ 145.00
9	REAR DOOR POWER WINDOW MOTOR C/W REGULATOR RH <i>new</i>	1	\$ 490.00	\$ 490.00
10	REAR DOOR OUTER STRIP RH <i>new</i>	1	\$ 110.00	\$ 110.00
11	REAR DOOR STICKER (BLACK) RH <i>new</i>	1	\$ 105.00	\$ 105.00
12	REAR DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 170.00	\$ 170.00
13	REAR FENDER RH <i>new</i>	1	\$ 896.30	\$ 896.30
14	REAR FENDER COWLING RH <i>new</i>	1	\$ 150.20	\$ 150.20
15	REAR FENDER ARCED GARNISH RH <i>new</i>	1	\$ 184.70	\$ 184.70
16	REAR ABS SENSOR RH <i>new</i>	1	\$ 430.00	\$ 430.00
17	REAR AXLE <i>new</i>	1	\$ 1,670.00	\$ 1,670.00
18	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 398.00	\$ 398.00
19	REAR WHEEL HUP COME WITH BEARING RH <i>new</i>	1	\$ 435.00	\$ 435.00
20	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 57.00	\$ 114.00

TOTAL PRICE \$ 8,266.20
LESS 20% \$ 1,653.24
SUB TOTAL PRICE \$ 6,612.96

3711.70

3017.36

1280

580

355

365

TO : EQ MOTOR CLAIMS DEPTS
 VEHICLE NO : SND8546C
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 05.12.2022
 TIME OF ACCIDENT : 23:25 HRS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR LOWER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>20</i>
2	REAR DOOR WHEEL ARCH GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>20</i>
3	REAR DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
4	REAR FENDER SEALANT <i>new</i>	1	\$ 180.00	\$ 180.00 <i>+</i>
5	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
6	REAR FENDER ARCED GARNISH CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>20</i>
7	REAR WHEEL RIM LH <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00 <i>550</i>
8	REAR WHEEL TYRE LH <i>hot an</i>	1	\$ 450.00	\$ 450.00 <i>x</i>
9	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00 <i>+</i>

640 TOTAL \$ 2,270.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 120.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>x</i>
7	TRANSFER REAR DOOR MECHANISM LH	\$ 80.00	<i>✓</i>
8	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>x 60</i>
9	TO PRESS REAR WHEEL BEARING	\$ 80.00	<i>x</i>
10	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>

TO : EQ MOTOR CLAIMS DEPTS
 VEHICLE NO : SND8546C
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 05.12.2022
 TIME OF ACCIDENT : 23:25 HRS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,110.00

TOTAL PARTS COST : \$ 8,882.96
 TOTAL LABOUR COST : \$ 5,110.00
 TOTAL REPAIR COST : \$ 13,992.96

1180

Adrian L
 H/s 07/12/22.
 04 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 4837.36
 c/s: 3850

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: