

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122012258/UQY3M4**Date:** 16/03/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG22004503
Claimant Vehicle No :	SJH5632H	Insured Vehicle No :	SMK3992E
Date of Loss:	02/12/2022	Nature of Claim:	TP
		Claim No:	CDMPG22002619

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH5632H	Engine No:	L13A4095615
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61085895
Reg. Date:	13/08/2008 (Man. Year: 2008)	Odometer:	198135 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,955.66	2,033.12	9,922.54	82.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,840.00	1,820.00	4,020.00	68.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,795.66	3,853.12	13,942.54	78.35
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	17,795.66	3,000.00	14,795.66	83.14

INSPECTION

Date of Assignment:	07/12/2022	
Date Inspected:	08/12/2022	Inspected At:
Estimated Period of Repair:	5.0 days	

13 KAKI BUKIT ROAD 4,
#01-04, BARTLEY BIZ CENTRE,
SINGAPORE 417807
REPAIRER: ZOOM AUTOWERKS PTE LTD

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2023)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH5632H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (TORN)	Not Consistent With The Impact	760.90 FL	*- FL
2	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	118.50 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT (BENT)	Not Consistent With The Impact	310.50 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	57.20 FL	*- FL
5	1		*FRONT BUMPER TOW HOOK COVER (TORN)	Not Consistent With The Impact	28.50 FL	*- FL
6	1		*FRONT FENDER -LH	Dented/Bent	571.50 FL	*440.20 FL
7	1		*FRONT FENDER BRACKET (N/S)	Not Necessary	46.80 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD (N/S)	Distorted	121.60 FL	*121.60 FL
9	1		*FRONT WHEEL HUB	Not Necessary	195.50 FL	*- FL
10	1		*FRONT WHEEL BEARING	Not Necessary	145.00 FL	*- FL
11	1		*FRONT SHOCK ABSORBER	Not Necessary	380.50 FL	*- FL
12	1		*FRONT KNUCKLE ARM	Not Necessary	385.00 FL	*- FL
13	1		*FRONT LOWER ARM	Not Necessary	346.50 FL	*- FL
14	1		*FRONT TIE ROD	Not Necessary	125.00 FL	*- FL
15	1		*FRONT DRIVE SHAFT -LH	Not Necessary	1,109.50 FL	*- FL
16	1		*FRONT DOOR -LH	Dented/Bent	1,046.90 FL	*862.20 FL
17	1		*FRONT DOOR CHECKER	Not Necessary	48.90 FL	*- FL
18	2		*FRONT DOOR HINGES	Not Necessary	77.40 FL	*- FL
19	1		*FRONT DOOR INNER BOARD	Not Necessary	662.50 FL	*- FL
20	1		*FRONT DOOR LOCK	Not Necessary	305.50 FL	*- FL
21	1		*FRONT DOOR OUTER HANDLE	Not Necessary	136.50 FL	*- FL
22	1		*FRONT DOOR REGULATOR WITH MOTOR	Not Necessary	440.40 FL	*- FL
23	1		*FRONT DOOR RUBBER	Necessary	165.50 FL	*132.20 FL
24	1		*ROCKER PANEL -LH	Repair	598.75 FL	*- FL
25	1		*REAR DOOR -LH	Dented/Bent	1,046.80 FL	*855.20 FL
26	1		*REAR DOOR CHECKER	Not Necessary	21.20 FL	*- FL
27	2		*REAR DOOR HINGES	Not Necessary	161.20 FL	*- FL
28	1		*REAR DOOR INNER BOARD	Not Necessary	235.12 FL	*- FL
29	1		*REAR DOOR LOCK	Not Necessary	298.50 FL	*- FL
30	1		*REAR DOOR REGULATOR WITH MOTOR	Not Necessary	414.90 FL	*- FL
31	1		*REAR DOOR RUBBER	Necessary	165.50 FL	*130.00 FL
32	1		*REAR FENDER -LH	Repair	891.50 FL	*- FL
33	1		*SET FRONT BUMPER CLIP	Not Necessary	35.00 FS	*- FS
34	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
35	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	35.00 FS	*- FS
36	1		*FRONT FENDER TOP QUARTER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
37	1		*FRONT TYRE	Not Necessary	400.00 FS	*- FS
38	1		*FRONT WHEEL RIM -LH	Repair	900.00 FS	*- FS
39	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
40	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
41	1		*REAR WHEEL RIM	Repair	900.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	0.00
2	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
4	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	350.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
6	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	120.00	0.00
7	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	120.00
8	TO APPLY UNDERCOATING	New	250.00	60.00
9	PANEL BEATING	New	2,200.00	600.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,000.00	900.00
Gross Labour Cost (S\$)			5,840.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >