

Vehicle Damage Assessment Report for [SJH5632H]

Estimate Created: 10/03/2023 14:40 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/03/2023 15:09 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Fit
Engine Type			
License Plate Number	SJH5632H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$3,000.00 WITH 5 WORKING
DAYS.

Insurlogic 4 (10/03/2023 15:09)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
LH front fender		1	440.20	-20.00 %	352.16
LH front fender inner shield		1	121.60	-20.00 %	97.28
LH front door		1	862.20	-20.00 %	689.76
LH front door rubber		1	132.20	-20.00 %	105.76
LH rear door		1	855.20	-20.00 %	684.16
LH rear door rubber		1	130.00	-20.00 %	104.00

Parts Subtotal 2,033.12

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove and refit inner garnish	RnR	80.00	0.00 %	80.00
To conduct wheel alignment	RnR	60.00	0.00 %	60.00
To remove and refit door fittings and replace damaged parts, transfer all the fittings to new door.	RnR	120.00	0.00 %	120.00
To apply undercoating	RnR	60.00	0.00 %	60.00
Panel beating	RnR	600.00	0.00 %	600.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
LH front wheel rim	Medium	0.00	0.00 %	0.00
LH rear fender	Medium	0.00	0.00 %	0.00
LH rear wheel rim	Medium	0.00	0.00 %	0.00
LH rocker panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To re-spray painting on the affected areas.	Full spray	900.00	0.00 %	900.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 920.00

Paint Labor Subtotal 900.00

Labor Subtotal 1,820.00

Summary

Repair Cost 3,853.12

Discount(22 %) (847.69)

3,005.43

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,005.43