



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized

5 January 2023

REG NO.: SJH 5632 H
MAKE/MODEL: HONDA FIT

*merus
8/12/23
1/5 \$3000 5 days.*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bumper <i>Torn n/c</i>	\$ 760.90 X
1	Front bumper centre grille <i>11</i>	\$ 118.50 X
1	Front bumper reinforcement <i>surf n/c</i>	\$ 310.50 X
2	Front bumper side retainers <i>11</i>	\$ 57.20 X
1	Front bumper tow hook cover <i>Torn n/c</i>	\$ 28.50 X
1	Front fender -LH <i>DD/3enf</i>	\$ 440.20 571.50
1	Front fender bracket <i>LH 11</i>	\$ 46.80 X
1	Front fender inner shield <i>LH 2.5</i>	\$ 121.60
1	Front wheel hub <i>11</i>	\$ 195.50 X
1	Front wheel bearing <i>11</i>	\$ 145.00 X
1	Front shock absorber <i>11</i>	\$ 380.50 X
1	Front knuckle arm <i>11</i>	\$ 385.00 X
1	Front lower arm <i>11</i>	\$ 346.50 X
1	Front tie rod <i>11</i>	\$ 125.00 X
1	Front drive shaft -LH <i>11</i>	\$ 1,109.50 X
1	Front door -LH <i>DD/3enf</i>	\$ 862.20 1,046.90
1	Front door checker <i>11</i>	\$ 48.90 X
2	Front door hinges <i>11</i>	\$ 77.40 X
1	Front door inner board <i>11</i>	\$ 662.50 X
1	Front door lock <i>11</i>	\$ 305.50 X
1	Front door outer handle <i>11</i>	\$ 136.50 X
1	Front door regulator with motor <i>11</i>	\$ 440.40 X
1	Front door rubber <i>11</i>	\$ 132.20 165.50
1	Rocker panel -LH <i>2</i>	\$ 598.75 X
1	Rear door -LH <i>DD/3enf</i>	\$ 855.20 1,046.80
1	Rear door checker <i>11</i>	\$ 21.20 X
2	Rear door hinges <i>11</i>	\$ 161.20 X
1	Rear door inner board <i>11</i>	\$ 235.12 X
1	Rear door lock <i>11</i>	\$ 298.50 X
1	Rear door regulator with motor <i>11</i>	\$ 414.90 X
1	Rear door rubber <i>11</i>	\$ 130.00 165.50
1	Rear fender -LH <i>2</i>	\$ 891.50 X
		\$ 11,419.57
	Less 20%	\$ 2,283.91
		\$ 9,135.66

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	11	\$	35.00	X
1	Front number plate with holder	11	\$	50.00	X
1	Front fender inner shield clip (1 set)	11	\$	35.00	X
1	Front fender top quarter glass sealant	11	\$	40.00	X
1	Front tyre	11	\$	400.00	X
1	Front wheel rim -LH	11	\$	900.00	X
1	Rear fender quarter glass sealant	11	\$	60.00	X
1	Rear tyre	11	\$	400.00	X
1	Rear wheel rim	11	\$	900.00	X
				<u>\$</u>	<u>2,820.00</u>

S/N**LABOUR CHARGES**

1	To check wiring and reset headlamps focusing.	\$	11	80.00	X
2	To remove, replaced damaged lamps and check up rear wiring.	\$	11	80.00	X
3	To remove and refit inner garnishes.	\$		180.00	80
4	To remove and refit front undercarriage.	\$	11	350.00	X
5	To conduct wheel alignment.	\$		180.00	60
6	To remove and refit quarter glass to assist repair.	\$	11	120.00	X
7	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$		400.00	120
8	To apply undercoating.	\$		250.00	60
9	Panel beating.	\$		2,200.00	600
10	To re-spray painting on the affected areas.	\$		2,000.00	900
				<u>\$</u>	<u>5,840.00</u>

GRAND TOTAL :**\$ 17,795.66**

LKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-2541.4
 202
 7-2033.12
 1-1820
 3813.12
 202
 3082