

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0271/2022
DATE : 07-DEC-2022

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : WONG KAI JUAN (HUANG KAIZHUANG)
ADDRESS : 238 WESTWOOD AVENUE
#12-41
S(648363)
TELEPHONE NO : 9687 7359

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SFU1771U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD92313
CHASSIS NO : JF1SJ5KC5JG110205
MILEAGE : 1 KM
DATE IN : 07/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 07/12/2022

Print Date : 07/12/2022
Print Time : 09:40:19

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST INDIA INT INS (SLP8933D)		
2	ZZ/001	DOA:05/12/2022 TIME:1131 HRS LOCATION:DOVER ROAD TOWARDS AYE		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL AND TAILGATE	2480.00	
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL AND TAILGATE	2160.00	
5	ZZ/004	TRANSFER (TAILGATE) MECHANISM	150.00	
6	ZZ/005	SUPPLY AND REPLACE REVERSE SENSOR - 2EYES	300.00	
7	ZZ/006	TO CONDUCT (REAR) LIGHTING TEST	50.00	
8	ZZ/007	TO CONDUCT WATER SEEPAGE TEST	100.00	
9	ZZ/008	FAULT DIAGNOSTIC (RESET)	280.00	
10	ZZ/009	TO CONDUCT (REAR) PROTECTANT COATING	500.00	
11	ZZ/011	SUNDRIES	100.00	
12	ZZ/10	TO CONDUCT (REAR) ANTI-RUST COATING	580.00	
		TOTAL LABOUR CHARGES	6700.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	SKIRT COMPL REAR END PANEL	52401SG0109P	296.00			
2	BUMPER FACE REAR FORESTER IL	57704SG012	555.00			
3	BRKT SD R RH	57707SG080	14.80			
4	BRKT SD R LH	57707SG090	14.80			
5	BEAM COMPL R EU	57711SG0219P	296.00			
6	COVER HOOK R	57731SG010NN	13.00			
7	COVER BMPR R (EXHAUST)	57731SG060	14.80			
8	PANEL CPL R/G NA	60809SG0109P	1102.60			
9	GLASS R/G	63019SG000	821.40			
10	RUBBER DAM GLS X2PCS	63232SG000	7.40			
11	CLIP BMPR * 9 PCS	909140007	21.60			
12	CLIP *2 PCS	909140062	6.00			
13	LETTER MARK FORESTOR R	93079SG000	40.70			
14	LETTER MK R SUB	93079SG030	66.60			
15	CARGO STEP PANEL (RESIN)FORESTER	E775ESG000	420.00			
SUB TOTAL			3690.70	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			738.14	0.00	0.00	0.00
GRAND TOTAL			2952.56	0.00	0.00	0.00
OVERALL TOTAL			2952.56			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFU1771U

TOTAL LABOUR CHARGES	6700.00
TOTAL SPARE PARTS CHARGES	2952.56
GRAND TOTAL	9652.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.