

(08/11/13) wef

ASS. REC. BY: AME

REF:

CCY/GRB 220/2262/2263

249C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SFU 17714at Workshop m/s MOTOR IMAGEof 25, LENH KEG RDInsured: 111

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 87K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SFU 17714

Yr Regn:

2018 / JunType: M / Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SUBARU FORESTER 2.0I-LS 1995

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

099673

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JFS1J5KC535116205Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S / Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/12/22

D.O.I.

09/12/22

Survey held at

MOTOR IMAGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 56K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0271/2022
DATE : 07-DEC-2022

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : WONG KAI JUAN(HUANG KAIZHUANG)
ADDRESS : 238 WESTWOOD AVENUE
#12-41
S(648363)
TELEPHONE NO : 9687 7359

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SFU1771U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD92313
CHASSIS NO : JF1SJ5KC5JG110205
MILEAGE : 1 KM
DATE IN : 07/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 07/12/2022

Print Date : 07/12/2022
Print Time : 09:40:19

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST INDIA INT INS (SLP8933D)		
2	ZZ/001	DOA:05/12/2022 TIME:1131 HRS LOCATION:DOVER ROAD TOWARDS AYE		
3	ZZ/002	REPLACE REAR BUMPER, BUMPER BEAM, END PANEL AND TAILGATE @600 x 2	2480.00	1800 1200
4	ZZ/003	RESPRAY REAR BUMPER, BUMPER BEAM, END PANEL AND TAILGATE @520 x 2	2160.00	1040
5	ZZ/004	TRANSFER (TAILGATE) MECHANISM	150.00	
6	ZZ/005	SUPPLY AND REPLACE REVERSE SENSOR - 2EYES	300.00	80
7	ZZ/006	TO CONDUCT (REAR) LIGHTING TEST	50.00	X11
8	ZZ/007	TO CONDUCT WATER SEEPAGE TEST	100.00	
9	ZZ/008	FAULT DIAGNOSTIC (RESET)	280.00	
10	ZZ/009	TO CONDUCT (REAR) PROTECTANT COATING	500.00	280?
11	ZZ/011	SUNDRIES	100.00	20
12	ZZ/10	TO CONDUCT (REAR) ANTI-RUST COATING	580.00	280?.
		TOTAL LABOUR CHARGES	6700.00	

AFTER MARKET AUTO TAILGATE CANNOT LOCK

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 SKIRT COMPL REAR END PANEL <i>bt</i>	52401SG0109P	296.00 ✓			
2 BUMPER FACE REAR FORESTER IL <i>de</i>	57704SG012	555.00 ✓			
3 BRKT SD R RH <i>ne</i>	57707SG080	14.80 ✓			
4 BRKT SD R LH <i>xan</i>	57707SG090	14.80			
5 BEAM COMPL R EU <i>?bt</i>	57711SG0219P	296.00 ✓			
6 COVER HOOK R <i>mis</i>	57731SG010NN	13.00 ✓			
7 COVER BMPR R (EXHAUST) <i>sur</i>	57731SG060	14.80 ✓			
8 PANEL CPL R/G NA <i>bt</i>	60809SG0109P	1102.60 ✓			
9 GLASS R/G <i>ne/ photo?</i>	63019SG000	821.40 ✓			
10 RUBBER DAM GLS X2PCS <i>ne</i>	63232SG000	7.40 ✓			
11 CLIP BMPR * 9 PCS <i>ne</i>	909140007	21.60 ✓			
12 CLIP *2 PCS <i>ne</i>	909140062	6.00 ✓			
13 LETTER MARK FORESTOR R <i>ne</i>	93079SG000	40.70 ✓			
14 LETTER MK R SUB <i>ne</i>	93079SG030	66.60 ✓			
15 CARGO STEP PANEL (RESIN)FORESTER <i>com</i>	E775ESG000	420.00 ✓			
SUB TOTAL		3690.70	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		738.14	0.00	0.00	0.00
GRAND TOTAL		2952.56	0.00	0.00	0.00
OVERALL TOTAL		2952.56			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFU1771U

TOTAL LABOUR CHARGES	6700.00
TOTAL SPARE PARTS CHARGES	2952.56

GRAND TOTAL	9652.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	01/12/22 @ 1400
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	5 days + 3 days = 8 days Resay before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT / BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 9489 9000
REFERENCE : INS/IC/CHI/0243/2022
DATE : 11 11 2022

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
S (049711)
TEL : 6347 6100
FAX :

OWNER'S NAME : WONG KAI JUAN (HUANG KAIZHUANG)
ADDRESS : X
X
SXXXXXX
TELEPHONE NO : X

TYPE OF CLAIMS : SUPPLEMENTARY CLAIMS
POLICY NO : XXXX
VEHICLE NO : SFU1771U
MODEL CODE : SJ5EK7C
MODEL / YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : XXXX
CHASSIS NO : XXXX
MILEAGE : XXXX KM
DATE IN : XXXX
LIABILITY : 0.00
EXCESS CLAUSE : -
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 27 10 2022

PRINT DATE : 30 12 2022
PRINT TIME : XXXXX

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE LABOUR CHARGES FOR ACCIDENT VEHICLE REG.NO SFU1771U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYORS RECOMMENDATIONS
1	zz/000	REPLACE REAR END PANEL & REPAIR SPARE TYRE FLOOR (2.0 SUPP)	1,200.00 ✓	
2	zz/000	RESPRAY REAR SPARE TYRE FLOOR & BUMPER BEAM (1.0 SUPP)	520.00 ✓	
3	zz/000	APPLY SEALANT TO EFFECTED AREA ✓	100.00 ✓	
4	zz/000	INTALL CARGO STEP PANEL ✓	60.00 ✓	
5	zz/000	REPLACE AUTO TAILAGTE SYSTEM ✓	723.00 ✓	

TOTAL LABOUR CHARGES

2,603.00