



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

MR ABDUL HALIM BIN LATIP
BLK 312 WOODLANDS ST 31
#02-42 (S) 730312

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SNE2106Z (India)
OUR REF : TP6459
VEHICLE NO : SME4365R
MAKE/MODEL : Mazda CX3
DATE OF ACCIDENT : 05.Dec.22

SURVEY BY

DATE : 07.Dec.22

1 PC TAILGATE	/ PD 1090	2357.00	S\$	1,090.00	
1 PC TAILGATE CENTRE EMBLEM	/ MC			65.00	
1 PC TAILGATE "CX3" EMBLEM	= 5 MC	1855.00		56.00	
1 PC TAILGATE "SKYACTIVE"				57.00	
1 PC REAR BUMPER	/ RL 1089			1,089.00	
2 PCS REAR BUMPER SIDE RETAINERS	X NN	35.00		70.00	
1 PC REAR BUMPER REINFORCEMENT	X NN			463.00	
			S\$	2,890.00	
	LESS 20%			578.00	
			S\$	2,312.00	
2 PCS TAILGATE SEALANT	/ MC	40.00	S\$	80.00	S/ NETT
1 PC REAR NUMBER PLATE	/ GSC			45.00	"
1 PC TAILGATE GLASS INNER SEAL	/ MC 193.00			40.00	"
1 SET REVERSE SENSORS	X NN			350.00	"
1 SET REAR BUMPER CLIPS	/ MC			28.00	"
			S\$	543.00	
TO REMOVE AND REFIT UPHOLYSTERY			S\$	80.00	60
TO REMOVE AND REFIX TAILGATE GLASS		1070.00		140.00	60 120
TO REMOVE AND REFIX PARKING SENSOR				60.00	40
TO CHECK WIRING FUNCTION				30.00	X
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL				80.00	X
ABOUT CHARGES				400.00	350
TO PUTTY AND SPRAY PAINTING CHARGES	P/P - \$3148.60			600.00	500
			S\$	4,245.00	

IN DOLLARS: FOUR THOUSAND TWO HUNDRED AND TWENTY-FIVE ONLY.

OUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

4 Days. 7/12/22
Put by mt.
before photo photos.
Gino Aiam
888082