

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01091/2022/EQ
DATE : 7-Dec-22
WIP : 53631

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PEH CHYE HENG
ADDRESS : 8 CACTUS DRIVE
#03-03
SINGAPORE 809686
TELEPHONE : HP +65 97329181
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800110079-02
VEHICLE NO : **SLS 6616 S**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 30/8/2018
ENGINE NO : CYG 024756
CHASSIS NO : WAUZZZ4G2JN060338
MILEAGE : 62,637
DATE IN : 5-Dec-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : LEBUHRAYA UTARA-SELATAN, TAMAN SERDANG
RAYA, SERI KEMBANGAN, SELANGOR, MALAYSIA

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250 500
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 6,400.00	2250 2750
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER, BONNET AND HINGES.	S/N \$ 5,000.00	2475 2575
TOTAL LABOUR CHARGES		\$ 14,280.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$ 480.00	
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	
TOTAL LABOUR CHARGES		: \$ 15,144.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	1	\$ 3,475.00	<i>2780.00</i>
2	FRONT BUMPER FIXING PARTS <i>Xan</i>	1	\$ 567.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>?Xan</i>	1	\$ 143.00	
4	FRONT BUMPER ADAPTER - LH / RH <i>?Xan</i>	2	\$ 84.00	
5	FRONT BUMPER CLOSING ELEMENT <i>cm-</i>	1	\$ 237.00	<i>189.20</i>
6	FRONT BUMPER LOWER SPOILER <i>repair</i>	1	\$ 276.00	
7	FRONT BUMPER LOWER TRIM SPOILER <i>Xan</i>	1	\$ 1,054.00	
8	RADIATOR GRILLE <i>cm-</i>	1	\$ 2,140.00	<i>1712.00</i>
9	RADIATOR GRILLE COVER <i>?cm/mis-</i>	1	\$ 41.00	<i>32.24</i>
10	RADIATOR GRILLE SENSOR SUPPORT - LH / RH <i>an-</i>	2	\$ 148.00	<i>117.92</i>
11	FRONT PARKING AID SENSOR - INNER <i>?Xan</i>	2	\$ 531.00	
12	FRONT PARKING AID SENSOR - OUTER <i>?Xan</i>	2	\$ 531.00	
13	FRONT PARKING AID SEAL RING <i>anXan</i>	4	\$ 6.00	
14	FRONT BUMPER WIRING SET <i>?Xan</i>	1	\$ 642.00	
15	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>an</i>	2	\$ 1,286.00	<i>514.00</i>
16	FRONT CHANNEL COVER - LH / RH <i>an</i>	2	\$ 116.00	<i>45.68</i>
17	FRONT WHEEL SPOILER - LH / RH <i>an</i>	2	\$ 588.00	<i>234.80</i>
18	FRONT BUMPER REINFORCEMENT BEAM <i>?Xan</i>	1	\$ 927.00	
19	FRONT BUMPER FOAM FILLER PIECE <i>?Xan</i>	1	\$ 265.00	
20	FRONT BUMPER BRACKET HOLDER - LH / RH <i>?Xan</i>	2	\$ 582.00	
SUB TOTAL SPARE PARTS		:	\$ 13,639.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACE - LH / RH ? Xan	2	\$ 68.00	
22	FRONT BUMPER GUIDE PIECE - LH / RH ? Xan	2	\$ 84.00	
23	FRONT BUMPER TOP COVER can	1	\$ 137.00	109.60
24	AIR CONDITIONER STICKER can	1	\$ 22.00	12.44
25	CAUTION SIGN STICKER can	1	\$ 16.00	12.40
26	HORN LOW TONE - LH ? Xan	1	\$ 214.00	
27	HORN HIGH TONE - RH ? Xan	1	\$ 214.00	
28	HORN BRACKET - LH / RH ? Xan	2	\$ 106.00	
29	FRONT FENDER - LH / RH Repair	2	\$ 3,120.00	
30	FRONT FENDER ATTACHMENT PARTS Xan	1	\$ 107.00	
31	FRONT FENDER BRACE - LH / RH Xan	2	\$ 214.00	
32	FRONT DOOR STONE GUARD FILM - LH / RH can	2	\$ 270.00	216.00
33	FRONT WHEEL HOUSING LINER - LH / RH ? Xan	2	\$ 620.00	
34	BONNET bt	1	\$ 5,736.00	4588.80
35	BONNET HINGE - LH / RH ? bt / (2pcs)	2	\$ 358.00	286.40
36	BONNET CATCH HOOK ? bt	1	\$ 155.00	124.00
37	BONNET LOCK - LH / RH can bt	2	\$ 455.00	182.00
38	BONNET LOCK BAR - LH / RH ? can bt	2	\$ 111.00	88.80
39	BONNET BOWDEN CABLE - CENTER ? Xan	1	\$ 64.00	
40	BONNET RELEASE CABLE COVER ? Xan	1	\$ 11.00	
SUB TOTAL SPARE PARTS		:	\$ 12,082.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET LOCK COVER ? Xn	1	\$ 4.00	
42	BONNET CATCH HOOK ? Xn	1	\$ 20.00	
43	BONNET LOCK CABLE ? Xn	1	\$ 82.00	
44	HEADLIGHT MOUNTING - LH / RH ? Xn	2	\$ 264.00	210.40
45	HEADLIGHT - LH / RH ? Xn	2	\$ 20,294.00	16,235.20
46	HEADLIGHT POWER MODULE ? Xn	1	\$ 635.00	
47	HEADLIGHT POWER MODULE ? Xn	1	\$ 625.00	
48	HEADLIGHT RANGE CONTROL MOTOR ? Xn	1	\$ 362.00	
49	HEADLIGHT FAN - RH ? Xn	1	\$ 428.00	
50	HEADLIGHT HOSE ? Xn	1	\$ 40.00	
51	HEADLIGHT ADJUSTMENT ELEMENT - LH / RH ? Xn	2	\$ 102.00	40.56
52	HEADLIGHT COMPENSATING PIECE RH - ? LH - ? 2 X	2	\$ 185.00	73.92
53	LIFT CYLINDER - LH / RH ? Xn	2	\$ 518.00	
54	LIFT CYLINDER COVER CAP - LH / RH ? Xn	2	\$ 128.00	
55	LIFT CYLINDER HOSE ? Xn	1	\$ 553.00	
56	LOCK CARRIER ca	1	\$ 1,385.00	1108.00
57	LOCK CARRIER SUPPORT - LH / RH ? Xn	2	\$ 83.00	
58	CHARGE AIR COOLER ? Xn	1	\$ 628.00	
59	PULSATION DAMPER X n	1	\$ 88.00	
60	CHARGE AIR COOLER PRESSURE PIPE - LH Xn	1	\$ 262.00	
SUB TOTAL SPARE PARTS		:	\$ 26,686.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER PRESSURE HOSE <i>X nn</i>	1	\$ 76.00	
62	A/C CONDENSER <i>bt</i>	1	\$ 829.00	<i>662.80</i>
63	A/C CONDENSER REFRIGERANT HOSE <i>? X nn</i>	1	\$ 286.00	
64	A/C CONDENSER REFRIGERANT PIPE <i>? X nn</i>	1	\$ 286.00	
65	OUTSIDE TEMPERATURE SENSOR BRACKET <i>? X nn</i>	1	\$ 26.00	
66	RADIATOR <i>bt - photo?</i>	1	\$ 897.00	<i>717.20</i>
67	READY-MIX COOLANT <i>re</i>	6	\$ 297.00	<i>237.12</i>
68	RADIATOR AIR GUIDE - LH / RH <i>cool</i>	2	\$ 172.00	<i>137.12</i>
69	RADIATOR AIR GUIDE SEALING STRIP <i>? X nn</i>	1	\$ 54.00	
70	RADIATOR AIR GUIDE COVER - UPPER CENTRE <i>? X nn</i>	1	\$ 32.00	
71	INTAKE AIR DUCT - RH <i>X nn</i>	1	\$ 101.00	
72	RADIATOR AIR GUIDE - RH <i>X nn</i>	1	\$ 31.00	
73	FRONT DISTANCE SENSOR - RH <i>? X nn</i>	1	\$ 7,495.00	
74	FRONT DISTANCE SENSOR FRAME COVER - RH <i>? X nn</i>	1	\$ 15.00	
75	FRONT NO PLATE <i>bt</i>	S/N	\$ 60.00	<i>✓</i>
76	SUNDRIES <i>? re</i>		\$ 500.00	<i>85.28</i>
TOTAL SPARE PARTS			: \$ 63,564.00	
TOTAL LABOUR CHARGES			: \$ 15,144.00	
GRAND TOTAL			: \$ 78,708.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Resue - 4g 90010068*
: *67/12/22 P 1630*
: *10 days*
: *EXCESS: TBA*
: *Revert*
: *Resue before paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01091/2022/EQ 12-Dec-22 CHANG 1 of 1 SLS 6616 S AUDI A6 1.8 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	FRONT REINFORCEMENT BEAM SUPPORT <i>cm</i> ✓	\$ 15.00	11.52
2	WATER DEFLECTOR <i>cm</i> ✓	\$ 84.00	67.12
GRAND TOTAL		\$ 99.00	

For Premium Automobiles Pte Ltd

Pau
12/12/22
Pu



Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 / 250 + 250 / PM	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 6,400.00 / 2250 @ 500 x 4.5	
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER, BONNET AND HINGES.	S/N \$ 5,000.00 / 2475 + 100. ✓	
TOTAL LABOUR CHARGES		\$ 14,280.00	

Reson
PM
12/12/22

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$ 480.00 /	
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 15,144.00	

Car-n

12/12/22.

mp=53631

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

A19 - Rasil

- 10 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER de-	1	\$ 3,475.00	
2	FRONT BUMPER FIXING PARTS X	1	\$ 567.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE ?	1	\$ 143.00	
4	FRONT BUMPER ADAPTER - LH / RH ?	2	\$ 84.00	
5	FRONT BUMPER CLOSING ELEMENT can	1	\$ 237.00	
6	FRONT BUMPER LOWER SPOILER repair	1	\$ 276.00	
7	FRONT BUMPER LOWER TRIM SPOILER X	1	\$ 1,054.00	
8	RADIATOR GRILLE can	1	\$ 2,140.00	
9	RADIATOR GRILLE COVER ? MIS	1	\$ 41.00	
10	RADIATOR GRILLE SENSOR SUPPORT - LH / RH can	2	\$ 148.00	
11	FRONT PARKING AID SENSOR - INNER ?	2	\$ 531.00	
12	FRONT PARKING AID SENSOR - OUTER ?	2	\$ 531.00	
13	FRONT PARKING AID SEAL RING can	4	\$ 6.00	
14	FRONT BUMPER WIRING SET ?	1	\$ 642.00	
15	FRONT BUMPER AIR GUIDE GRILLE - LH / RH MIS	2	\$ 1,286.00	
16	FRONT CHANNEL COVER - LH / RH can	2	\$ 116.00	
17	FRONT WHEEL SPOILER - LH / RH ? can	2	\$ 588.00	
18	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 927.00	
19	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 265.00	
20	FRONT BUMPER BRACKET HOLDER - LH / RH ?	2	\$ 582.00	
SUB TOTAL SPARE PARTS		:	\$ 13,639.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACE - LH / RH ?	2	\$	68.00
22	FRONT BUMPER GUIDE PIECE - LH / RH ?	2	\$	84.00
23	FRONT BUMPER TOP COVER <i>cond</i>	1	\$	137.00
24	AIR CONDITIONER STICKER <i>ac</i>	1	\$	22.00
25	CAUTION SIGN STICKER <i>ac</i>	1	\$	16.00
26	HORN LOW TONE - LH ?	1	\$	214.00
27	HORN HIGH TONE - RH ?	1	\$	214.00
28	HORN BRACKET - LH / RH ?	2	\$	106.00
29	FRONT FENDER - LH / RH <i>Repair</i>	2	\$	3,120.00
30	FRONT FENDER ATTACHMENT PARTS X	1	\$	107.00
31	FRONT FENDER BRACE - LH / RH X	2	\$	214.00
32	FRONT DOOR STONE GUARD FILM - LH / RH <i>acc</i>	2	\$	270.00
33	FRONT WHEEL HOUSING LINER - LH / RH ?	2	\$	620.00
34	BONNET <i>bt</i>	1	\$	5,736.00
(35)	BONNET HINGE (LH) (RH) <i>R. & L. bt (2 pcs)</i>	2	\$	358.00
(36)	BONNET CATCH HOOK <i>bt</i>	1	\$	155.00
37	BONNET LOCK - LH / RH <i>bt</i>	2	\$	455.00
38	BONNET LOCK BAR - LH / RH ?	2	\$	111.00
39	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00
40	BONNET RELEASE CABLE COVER ?	1	\$	11.00
SUB TOTAL SPARE PARTS		:	\$	12,082.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET LOCK COVER ?	1	\$ 4.00	
42	BONNET CATCH HOOK ?	1	\$ 20.00	
43	BONNET LOCK CABLE ?	1	\$ 82.00	
44	HEADLIGHT MOUNTING LH/RH Ca	2	\$ 264.00	
45	HEADLIGHT LH/RH Ca	2	\$ 20,294.00	
46	HEADLIGHT POWER MODULE ?	1	\$ 635.00	
47	HEADLIGHT POWER MODULE ?	1	\$ 625.00	
48	HEADLIGHT RANGE CONTROL MOTOR ?	1	\$ 362.00	
49	HEADLIGHT FAN - RH ?	1	\$ 428.00	
50	HEADLIGHT HOSE ?	1	\$ 40.00	
51	HEADLIGHT ADJUSTMENT ELEMENT - LH/RH Ca	2	\$ 102.00	
52	HEADLIGHT COMPENSATING PIECE RH - Ca / LH - ? 2	2	\$ 185.00	
53	LIFT CYLINDER - LH / RH ?	2	\$ 518.00	
54	LIFT CYLINDER COVER CAP - LH / RH ?	2	\$ 128.00	
55	LIFT CYLINDER HOSE ?	1	\$ 553.00	
56	LOCK CARRIER Ca	1	\$ 1,385.00	
57	LOCK CARRIER SUPPORT - LH / RH ?	2	\$ 83.00	
58	CHARGE AIR COOLER ?	1	\$ 628.00	
59	PULSATION DAMPER X	1	\$ 88.00	
60	CHARGE AIR COOLER PRESSURE PIPE - LH X	1	\$ 262.00	
SUB TOTAL SPARE PARTS		:	\$ 26,686.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER PRESSURE HOSE X	1	\$ 76.00	
62	A/C CONDENSER bt ✓	1	\$ 829.00	
63	A/C CONDENSER REFRIGERANT HOSE ?	1	\$ 286.00	
64	A/C CONDENSER REFRIGERANT PIPE ?	1	\$ 286.00	
65	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 26.00	
66	RADIATOR bt - photo? ✓	1	\$ 897.00	
67	READY-MIX COOLANT re ✓	6	\$ 297.00	
68	RADIATOR AIR GUIDE - LH / RH cor ✓	2	\$ 172.00	
69	RADIATOR AIR GUIDE SEALING STRIP ?	1	\$ 54.00	
70	RADIATOR AIR GUIDE COVER - UPPER CENTRE ?	1	\$ 32.00	
71	INTAKE AIR DUCT - RH X	1	\$ 101.00	
72	RADIATOR AIR GUIDE - RH X	1	\$ 31.00	
73	FRONT DISTANCE SENSOR - RH ?	1	\$ 7,495.00	
74	FRONT DISTANCE SENSOR FRAME COVER - RH ?	1	\$ 15.00	
75	FRONT NO PLATE bt ✓	S/N	\$ 60.00	
76	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 63,564.00	
TOTAL LABOUR CHARGES		:	\$ 15,144.00	
GRAND TOTAL		:	\$ 78,708.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.