

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01086/2022/EQ
DATE : 5-Dec-22
WIP : 53536

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul
7 days - ok - Johnny Boo
10-Feb-23

OWNER'S NAME : MR SELVARATNAM SUTHESH ARTHUR
ADDRESS : 167 TAI KENG GARDENS
SINGAPORE 535439

TELEPHONE : HP +65 90265601
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900260824-03
VEHICLE NO : **SLN 7781 S**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 27/12/2019
ENGINE NO : CVK 088156
CHASSIS NO : WAUZZZF50KA079006
MILEAGE : -
DATE IN : 5-Dec-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Dec-22
PLACE OF ACCIDENT : ROCHDALE ROAD AND UPPER PAYA LEBAR ROAD
JUNCTION/INTERSECTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 7781 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,600.00	
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
5	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$	280.00	\$ 280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$ 1,500.00
TOTAL LABOUR CHARGES		: \$	8,640.00	\$ 2,790.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 7781 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 2,790.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES, LHS UPPER A-PILLAR AND LHS FRONT DOOR.	\$	5,000.00	\$ 2,200.00
8	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 14,352.00	\$ 5,182.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7781 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00		
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 72.00	\$	57.20
7	RADIATOR GRILLE	1	\$ 2,576.00	\$	2,060.80
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 116.00		
9	RADIATOR GRILLE COVER - UPPER	1	\$ 209.00		
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 529.00	\$	423.20
11	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00		
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
14	FRONT BUMPER TOP COVER	1	\$ 143.00		
15	CAUTION SIGN STICKER	1	\$ 16.00		
16	AIR CONDITIONER STICKER	1	\$ 9.00		
17	LOCK CARRIER BRACKET	1	\$ 154.00		
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
19	HORN HIGH TONE - LH	1	\$ 134.00		
20	HORN BRACKET - LH	1	\$ 33.00		
SUB TOTAL SPARE PARTS		:	\$ 8,604.00	\$	4,567.84

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7781 S

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	4,567.84
21	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$	532.00	
22	FRONT PARKING AID SEAL RING	4	\$	10.00	
23	FRONT BUMPER WIRING SET	1	\$	567.00	
24	FRONT FENDER - LH	1	\$	1,189.00	\$ 951.20
25	FRONT FENDER ATTACHMENT PARTS	1	\$	55.00	
26	FRONT FENDER CLOSING ELEMENT - LH	1	\$	83.00	\$ 65.84
27	FRONT FENDER BRACKET - LH FRONT	1	\$	41.00	\$ 32.72
28	FRONT FENDER RIVET	6	\$	23.00	\$ 18.24
29	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$	55.00	
30	FRONT FENDER BRACKET - LH CENTER	1	\$	40.00	
31	FRONT FENDER BRACE - LH	1	\$	132.00	\$ 105.20
32	FRONT WHEEL HOUSING LINER - LH	1	\$	299.00	\$ 238.80
33	FRONT WHEEL SPOILER - LH	1	\$	82.00	\$ 65.12
34	FRONT WHEEL SPOILER END PLATE - LH	1	\$	39.00	\$ 31.12
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH	1	\$	57.00	
36	FRONT WHEEL SPOILER TRIM BRACKET - LH	1	\$	27.00	
37	FRONT FENDER LEDGE COVER - LONG	1	\$	40.00	
38	FRONT FENDER LEDGE COVER - SHORT	1	\$	18.00	\$ 13.92
39	BONNET	1	\$	3,491.00	\$ 2,792.80
40	BONNET HINGE - LH / RH	2	\$	932.00	
SUB TOTAL SPARE PARTS		:	\$	7,712.00	\$ 8,882.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7781 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>8,882.80</i>
41	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	<i>\$</i>	<i>73.20</i>
42	BONNET SOUND ABSORBER	1	\$ 382.00		
43	BONNET STRIKER - LH	1	\$ 56.00		
44	BONNET LOCK	1	\$ 228.00		
45	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
46	BONNET RELEASE LEVER	1	\$ 15.00		
47	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
48	BONNET RELEASE CABLE COVER	1	\$ 11.00		
49	BONNET LOCK CABLE	1	\$ 82.00		
50	PLENUM CHAMBER COVER	1	\$ 108.00		
51	HEADLIGHT - LH	1	\$ 8,416.00	<i>\$</i>	<i>6,732.80</i>
52	HEADLIGHT POWER MODULE	1	\$ 850.00		
53	HEADLIGHT CONTROL UNIT	1	\$ 840.00		
54	HEADLIGHT HEAT SINK - LH	1	\$ 1,281.00		
55	HEADLIGHT HOSE	1	\$ 42.00		
56	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
57	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
58	HEADLIGHT COMPENSATING PIECE	1	\$ 47.00		
59	LIFT CYLINDER - LH	1	\$ 217.00		
60	LIFT CYLINDER BRACKET - LH	1	\$ 17.00	<i>\$</i>	<i>12.88</i>
SUB TOTAL SPARE PARTS		:	\$ 12,903.00	<i>\$</i>	<i>15,701.68</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7781 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>15,701.68</i>
61	LIFT CYLINDER CORRUGATED PIPE	1	\$ 100.00		
62	LOCK CARRIER	1	\$ 1,478.00		
63	LOCK CARRIER SUPPORT - LH	1	\$ 43.00		
64	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
65	A/C REFRIGERANT LINE	1	\$ 186.00		
66	A/C REFRIGERANT LINE	1	\$ 381.00		
67	A/C REFRIGERANT LINE	1	\$ 277.00		
68	A/C REFRIGERANT PIPE	1	\$ 585.00	<i>\$</i>	<i>468.00</i>
69	A/C LINE BRACKET	1	\$ 9.00	<i>\$</i>	<i>6.48</i>
70	A/C CONDENSER	1	\$ 683.00		
71	READY-MIX COOLANT	6	\$ 297.00		
72	RADIATOR AIR GUIDE - LH INNER	1	\$ 36.00		
73	RADIATOR AIR GUIDE - LH OUTER	1	\$ 19.00		
74	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00		
75	FRONT FENDER CHROME TRIM - LH	1	\$ 171.00	<i>\$</i>	<i>136.40</i>
76	FRONT DOOR CHROME TRIM - LH	1	\$ 171.00	<i>\$</i>	<i>136.40</i>
77	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH	1	\$ 446.00		
78	FRONT NO PLATE	S/N	\$ 60.00	<i>\$</i>	<i>60.00</i>
79	SUNDRIES		\$ 500.00	<i>\$</i>	<i>67.28</i>
TOTAL SPARE PARTS			\$ 34,701.00	<i>\$</i>	<i>16,576.24</i>
TOTAL LABOUR CHARGES			\$ 14,352.00	<i>\$</i>	<i>5,182.00</i>
GRAND TOTAL			\$ 49,053.00	<i>\$</i>	<i>21,758.24</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-30/12/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT