



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LIBERTY INSURANCE PTE LTD  
51 CLUB STREET, #03-00  
LIBERTY HOUSESINGAPORE 069428

Ref: CS/LIP22012269/Rvy3m4

Date: 13/06/2023

Code: LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLC 8490H	<b>Veh. Inspected</b>	XE 5968P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	AVS22/3096	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANDY SEAH	<b>Assign Date</b>	07/12/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ AROCS 2630 6X4	<b>c.c</b>	7698
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>	W1T96401420463100	<b>Colour</b>	GREY
<b>Odometer</b>	136562 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	315/80R22.5	FIREMAX	8 mm
<b>L/H Front Tyre</b>	315/80R22.5	FIREMAX	8 mm
<b>R/H Rear Tyre</b>	315/80R22.5 (D/D)	FIREMAX	8/8 mm
<b>L/H Rear Tyre</b>	315/80R22.5 (D/D)	FIREMAX	8/8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	02/11/2022	<b>Inspection Date</b>	08/12/2022
<b>Survey held at</b>	17 TUAS AVENUE 12 SINGAPORE 639037		
<b>Repairer</b>	SEMBWASTE PTE LTD		

### 5a. Remarks

A)REGISTRATION DATE: 20 NOV 2020  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------