



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012273/Uqy3m4	
			Date: 23/03/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 5576S	Veh. Inspected	SKB 6266U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/12/22/2010	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	08/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 6 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JM6GL1073L0400132	Colour	BROWN	
Odometer	12453 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	7 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/12/2022	Inspection Date	08/12/2022	
Survey held at	TRANS EUOKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	