



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP22012277/Uny3m4	
BLK 1 KAKI BUKIT AVE 6			Date: 09/01/2023	
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF TAN KAY GUAN			Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected		SLN 9706Y
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		12/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 6 SP (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6GL1071H0103511	Colour	SILVER	
Odometer	88102 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/55 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/55 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/55 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/12/2022	Inspection Date	12/12/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	