

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435, 91896243

TAX INVOICE

Repair Code : CLM17508
Date in : 07/12/2022
Vehicle Num. : SNG2467X
Model : TOYOTA SIENTA HYBRID STANDARD (AUTO)
Chassis/Eng# : JTDZZ9H380L001153/1NZ9412165

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER	1	675 750.00	de 750.00
REAR BUMPER CENTER PROTECTOR GARNISH	1	186.30 207.00	de 207.00
REAR BUMPER REFLECTOR L/R	2	85.00	X UN 170.00
REAR BUMPER RH END SEAL COVER	1	81.00	X UN 81.00
REAR BUMPER SIDE PROTECTOR GARNISH L/R	2	135.90 151.00	de 302.00
REAR BUMPER SIDE RETAINER L/R	2	82.80 90.00	de 165.60
REAR BUMPER TOW HOOK COVER	1	25.00	X UN 25.00
REAR DECK TOP TRIM BOARD	1	617.40 686.00	de 686.00
REAR END INNER PANEL	1	626.40 696.00	de 696.00
REAR END OUTER PANEL	1	410.40 456.00	de 456.00
REAR END PANEL TOP GARNISH	1	139.50 155.00	de 155.00
REAR FENDER INNER TRIM BOARD L/R	2	592.20 658.00	de 1184.40
REAR SPARE WHEEL PANEL	1	422.10 778.70	de 778.70
REAR SPARE WHEEL TOOL BOX	1	469.00	de 469.00
REAR SPARE WHEEL TOOL BOX RH TOP TRIM BOARD	1	278.00	X UN 278.00
REAR TAILGATE	1	1018.71 1131.90	de 1,131.90
REAR TAILGATE 'HYBRID' EMBLEM	1	51.30 57.00	de 57.00
REAR TAILGATE 'LOGO' EMBLEM	1	60.75 67.50	de 67.50

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
 53 UBI AVENUE 1 #03-47 PAYA UBI
 INDUSTRIAL PARK
 SINGAPORE 408934

Contact : 87420435, 91896243

TAX INVOICE

Repair Code : CLM17508

Date in : 07/12/2022

Vehicle Num. : SNG2467X

Model : TOYOTA SIENTA HYBRID STANDARD (AUTO)

Chassis/Eng# : JTDZZ9H380L001153/1NZ9412165

REAR TAILGATE INNER PULL HANDLE	1	43.20	48.00	all	48.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	2		19.00	x un	38.00
REAR TAILGATE INNER TRIM BOARD	1		138.00	x un	138.00
REAR TAILGATE LOCK STRIKER	1		25.80	ut x	25.80
REAR TAILGATE MECHANISM LOCK	1	420.84	467.60	bt	467.60
REAR TAILGATE OUTER GARNISH	1	186.30	207.00	cu	207.00
REAR TAILGATE REFLECTOR L/R	2	252.90	281.00	cut	562.00
REAR TAILGATE WEATHER STRIP	1	346.50	385.00	twi	385.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	45	50.00	un	100.00
REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER)	2	40.50	45.00	un	90.00
REAR TAILLAMP L/R	2	382.50	425.00	RM	850.00
REAR TAILLAMP LOWER BRACKET L/R	2	74.79	83.10	de	166.20
REAR TAILLAMP OUTER PANEL SIDE STOPPER	2		42.90	x un	85.80
		Subtotal before discount		8031.78	10,969.50
Percentage discount 25%				2007.93	2,742.38
		Sub-total 1			8,227.13
REAR BUMPER CLIPS - SET	1		50.00	300	50.00
REAR BUMPER REVERSE SENSOR	1		300.00	200nw	300.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435, 91896243

TAX INVOICE

Repair Code : CLM17508

Date in : 07/12/2022

Vehicle Num. : SNG2467X

Model : TOYOTA SIENTA HYBRID STANDARD (AUTO)

Chassis/Eng# : JTDZZ9H380L001153/1NZ9412165

REAR BUMPER TOP RUBBER PAD	1	150.00	60.00	150.00
REAR END PANEL SEALANT	1	80.00	40.00	80.00
REAR END PANEL TOP GARNISH CLIPS - SET	1	30.00	20.00	30.00
REAR FENDER TRIM GARNISH CLIPS L/R - SET	2	50.00	X 100.00	100.00
REAR SPARE WHEEL PANEL INSULATOR MAT	1	200.00	100.00	200.00
REAR SPARE WHEEL PANEL SEALANT	1	80.00	X 7	80.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	X	50.00
REAR TAILGATE NUMBER PLATE	1	35.00	X	35.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	X	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	30.00	X	30.00
REAR TAILGATE RUBBER MOULDING	1	120.00	X	120.00
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	40.00	60.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	30.00	60.00
Subtotal before discount			520	1,395.00
Percentage discount 0%				0.00
Sub-total 2				1,395.00
Parts-total				9,622.13

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435, 91896243

TAX INVOICE

Repair Code : CLM17508

Date in : 07/12/2022

Vehicle Num. : SNG2467X

Model : TOYOTA SIENTA HYBRID STANDARD (AUTO)

Chassis/Eng# : JTDZZ9H380L001153/1NZ9412165

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

30 80.00

To remove, reinstall tailgate windscreen

120 150.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 140.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

950 1,400.00

To remove and reinstall exhaust pipe.

put 60 100.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

950 1,600.00

To apply anti-rust chemical on repaired and replaced panel.

40 100.00

To remove, reinstall tailgate mechanism and check for function

60 80.00

Labour Total

3,650.00

Parts & Labour Total

13,272.13

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

page 4

Tanpin 97415749
up 8/12/22
LLS Repair after report
Tanpin 21khafo-wu
7 days

6023.83
520
2210
8753.83
7000
7 days