

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A16 22012283/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

5 757X

Vehicle: IN / OUT

1-11-42944

Date / Time

Action / Instruction

Rep 10k.

20/12/22 2/5 @ 2700 informed MR Ray

Veh No: GBL 7302X

Yr Regn: 04/03/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

KIA K2500

c.c 2497

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

23403

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNCSJX76LM7560658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

145 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

2

mm

R/Bal.

2/2

mm

L/Bal.

2

mm

L/Bal.

2/2

mm

D.O.A.

03/12/22

D.O.I.

8/12/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :

Page : 1/2

Our Ref : TP0071/12/22

Date : 08/12/2022

THIRD PARTY CLAIM

M/S : JJ CONSTRUCTION PTE. LTD.
175A Bencoolen Street
#08-06 Burlington Square Singapore 189650

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBL7302X - KIA K250
INSURED : JJ CONSTRUCTION PTE. LTD.
DATE OF ACCIDENT : 03/12/2022
POLICY NO :

ENGINE# :

CHASSIS# :

*not follow
8/12/22
1/38 2700
4 days
who photo after 14-*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

		Qty	U/Cost	U/Price	Total
			\$	\$	\$
<u>Replacement of Parts</u>					
1	rear cabin tailgate center door	10/341 1050	1299.00	1299.00	1,299.00 ✓
2	rear 70 sticker	na	147.00	147.00	147.00 1050/W
3	rear lamp panel o/s	341	221.00	221.00	221.00
4	rear lamp assembly na o/s	one	169.00	169.00	169.00
5	rear number plate lamp	cut	51.00	51.00	51.00
6	rear tailgate door lower body panel	na	221.00	221.00	221.00 X
7	rear cabin lower step support bar	341	399.00	399.00	399.00
8	rear cabin tailgate door top rubber	341	480.00	480.00	480.00
					2,987.00
Less 10%					-298.70
<u>Total Material</u>					\$2,688.30

Special Nett Items

1	rear parking sensor	shall	10	200.00	200.00	200.00 ✓
						200.00

Total S/Nett

\$200.00

Labour & Misc

1	Remove and install rear door, rear lamp, rear lamp panel, rear step bar, cut out and renew rear cabin inner panel, knocking rear cabin floorboard, restraighthen body and chassis.	580	850.00
2	Spray painting	450	750.00
3	Check wiring system	20	25.00
4	Remove and install rear cabin and re-adjust rear cabin.	17 X	450.00
			2,075.00

*P- 2370
102
2133
210
1050
3393*



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Our Ref : TP0071/12/22

Page : 2/2

Date : 08/12/2022

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
				0.00
Total Labour				\$2,075.00
Nett Total Before Gst				\$4,963.30

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: