

ASSIGNMENT

06-2026/may

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: 4P 28377

at Workshop m/s Sinh AH TEE

of 3, Pioneer RD North #01-18

Insured: ECI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 59K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time _____ Action / Instruction

REPAIR LIMIT - 45K

Veh No: 4P 28377 Yr Regn: 2016 may

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI Canter Feb 21 c.c. 2998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 321547 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21 EA 20604

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Contour

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 30/11/22 D.O.I. 09/12/22

Survey held at Sinh AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS, SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Insp (\$ _____)

) Others

☐ : Workshop (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCGH22004909	Date of Loss:	30/11/2022
Vehicle Reg. No.:	YP2837J	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THERMAL TECH ENGINEERING PTE. LTD.	Contact No:	+6592264051
Driver:	GANESAN SEVAMANI		

Make/Model:	MITSUBISHI FEB21ER3SDEN, 3.0 D (A)	Vehicle Reg. Date:	27/05/2016
Vehicle Colour:	WHITE		
Engine No:	4P10C21813	Chassis No:	FEB21EA20604
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	15,445.80
Miscellaneous Items	0.00
Labour	3,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	19,345.80
+ GST 7.00% (\$\$)	1,354.21
Nett Amount (\$\$)	20,700.01

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Dec 2022)
Parts:	N/A MITSUBISHI FEB21ER3SDEN 3.0 D (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER SIDE COVER LH	0.00	0.00	*180.00 F
2	1		*FRT CORNER PANEL LH	0.00	0.00	*240.00 F
3	1		*FRT CORNER PANEL TOP COVER LH	0.00	0.00	*28.00 F
4	1		*FRT CORNER PANEL SEAL LH	0.00	0.00	*25.00 F
5	1		*FRT SIDE MIRROR ARM LH	0.00	0.00	*405.00 F
6	1		*FRT SIDE MIRROR RETANGULAR LH	0.00	0.00	*60.00 F
7	1		*FRT SIDE MIRROR ROUND LH	0.00	0.00	*35.00 F
8	1		*FRT SIDE MIRROR ROUND COVER LH	0.00	0.00	*12.00 F
9	1		*FRT HEADLAMP LH	0.00	0.00	*230.00 F
10	1		*FRT HEADLAMP LOWER APRON LH	0.00	0.00	*8.00 F
11	1		*FRT SIGNAL LAMP LH	0.00	0.00	*150.00 F
12	1		*FRT REFLECTOR LH	0.00	0.00	*110.00 F
13	1		*FRT PANEL FUSO STICKER	0.00	0.00	*105.00 F
14	1		*FRT DOOR LH	0.00	0.00	*1,050.00 F
15	1		*FRT DOOR UPPER HINGE LH	0.00	0.00	*75.00 F
16	1		*FRT DOOR LOWER HINGE LH	0.00	0.00	*75.00 F
17	1		*FRT DOOR CHECKER LH	0.00	0.00	*34.00 F
18	1		*FRT DOOR INNER TRIM BOARD LH	0.00	0.00	*280.00 F
19	1		*FRT DOOR UPPER ARMREST LH	0.00	0.00	*250.00 F
20	1		*FRT DOOR LOCK LH	0.00	0.00	*220.00 F
21	1		*FRT DOOR RUBBER LH	0.00	0.00	*190.00 F
22	1		*FRT DOOR INNER TRIM SEAL LH	0.00	0.00	*125.00 F
23	1		*FRT DOOR GLASS LH	0.00	0.00	*265.00 F
24	1		*FRT DOOR GLASS INNER MOULDING LH	0.00	0.00	*70.00 F
25	1		*FRT DOOR GLASS OUTER MOULDING LH	0.00	0.00	*75.00 F
26	1		*FRT DOOR GLASS RUN CHANNEL LH	0.00	0.00	*120.00 F
27	1		*FRT DOOR GLASS REGULATOR LH	0.00	0.00	*820.00 F
28	1		*FRT DOOR GLASS MOTOR LH	0.00	0.00	*770.00 F
29	1		*FRT DOOR CIGRATTE LIGHTER TRAY LH	0.00	0.00	*120.00 F
30	1		*FRT DOOR GARNISH @FRT LH	0.00	0.00	*20.00 F
31	1		*FRT DOOR GARNISH @RR LH	0.00	0.00	*26.00 F
32	1		*FRT STEP GARNISH LH	0.00	0.00	*280.00 F
33	1		*FRT SCUFF PLATE LH	0.00	0.00	*90.00 F
34	1		*FRT PILLAR INNER LH	0.00	0.00	*600.00 F
35	1		*FRT PILLAR INNER TRIM LH	0.00	0.00	*80.00 F
36	1		*FRT PILLAR OUTER LH	0.00	0.00	*700.00 F
37	1		*FRT WINDSCREEN	0.00	0.00	*500.00 F
38	1		*FRT WINDSCREEN RUBBER	0.00	0.00	*195.00 F
39	1		*FRT INSTRUMENT COVER LH	0.00	0.00	*350.00 F
40	1		*AIRCON BLOWER	0.00	0.00	*950.00 F
41	1		*ERP BRACKET	0	0.00	*26.00 FS
42	1		*HEATER BLOWER	0.00	0.00	*1,300.00 F
43	1		*AIRCON COWLING COIL ASSY	0.00	0.00	*1,600.00 F
44	1		*FRT PANEL	0.00	0.00	*1,200.00 F

F=Franchise part. S=SpcNett.

o.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
			Sub Total (S\$)			14,044.00
			+ Margin on L,N Items 10.00% (S\$)			1,401.80
			Total Parts (S\$)			15,445.80

Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK FRT CABIN RR PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New	1,600.00 1000
2	TO SPRAY PAINTING FRT CORNER PANEL,FRT PANEL,FRT DOOR LH,FRT PILLAR LH, AND AFFECTED AREAS	New	1,500.00 1200
3	TO CHECK WIRING	New	30.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	220.00 150
5	TO TOP UP AIR CON GAS	New	100.00 ?
6	TO REMOVE & REFIX UPHOSTERY	New	100.00 60
7	TO REMOVE & REPLACE FRT WINDSCREEN	New	120.00
8	TO REMOVE & REFIX FRT DOOR GLASS	New	80.00 60
9	TO DIAGNOSE & RESET FAULT CODE	New	150.00 100
Gross Labour Cost (\$\$)			3,900.00

Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
Hp 90010068
10 days
4/5
09/12/22 @ 1200
EXCESS: TDA
Revert
Resur after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 328N

Vehicle Details

Vehicle No.: YP2837J

Vehicle to be Exported: No

Intended Deregistration Date: 28 Jan 2023

Vehicle Make: MITSUBISHI

Vehicle Model: CANTER FEB21ER4SDEB (CBU)

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 4P10C21813

Chassis No.: FEB21EA20604

Maximum Power Output: -

Open Market Value: \$32,616.00

Original Registration Date: 27 May 2016

First Registration Date: 27 May 2016

Transfer Count: 1

Actual ARF Paid: \$1,631.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$40,897.00

COE Rebate Amount: \$13,600.00

Total Rebate Amount: \$13,600.00

Mitsubishi Fuso Canter FEB21

Overview

Financial

Accessories

Similar

Research

Photos

Map



Envision your ideal vehicle.

Price	\$56,800	Lifespan ?	30-Mar-2036
Depreciation ?	\$17,200 /yr View models with similar depre	Reg Date	31-Mar-2016 (3yrs 3mths 19days COE left)
Mileage	N.A.	Manufactured ?	2014
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$6,817 as of today (change)	Fuel Type	Diesel
COE ?	\$20,649	OMV ?	\$31,967
Engine Cap	2,998 cc	ARF ?	\$1,599
Curb Weight ?	2,500 kg	No. of Owners ?	1