

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ivy Yong

Date: 12 Dec 2022

**Preliminary Advice**

Vehicle No	: YP2837J	Accident Date	: 30/11/2022
Make	: MITSUBISHI FEB21ER3SDEN	Policy No.	: DMCGH22004909
Assignment Date	: 08/12/2022	Excess	: S\$0.00
Date of Inspection	: 09/12/2022	Est. Duration of Repair	: 10
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,345.80
Revised Amount	:S\$	8,554.00
Check Items (Estimated)	:S\$	5,332.70
Total	:S\$	13,886.70

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	13,600.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,400.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.