

Ramul LKK 01/08/20

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Dec 2022)
Parts:	N/A MITSUBISHI FEB21ER3SDEN 3.0 D (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER SIDE COVER LH <i>see</i>	0.00	0.00	*180.00 F✓
2	1		*FRT CORNER PANEL LH <i>see</i>	0.00	0.00	*240.00 F✓
3	1		*FRT CORNER PANEL TOP COVER LH <i>see</i>	0.00	0.00	*28.00 F✓
4	1		*FRT CORNER PANEL SEAL LH <i>see</i>	0.00	0.00	*25.00 F✓
5	1		*FRT SIDE MIRROR ARM LH <i>see</i>	0.00	0.00	*405.00 F✓
6	1		*FRT SIDE MIRROR RETANGULAR LH <i>see</i>	0.00	0.00	*60.00 F✓
7	1		*FRT SIDE MIRROR ROUND LH <i>see</i>	0.00	0.00	*35.00 F✓
8	1		*FRT SIDE MIRROR ROUND COVER LH <i>see</i>	0.00	0.00	*12.00 F✓
9	1		*FRT HEADLAMP LH ?	0.00	0.00	*230.00 FX
10	1		*FRT HEADLAMP LOWER APRON LH ?	0.00	0.00	*8.00 FX
11	1		*FRT SIGNAL LAMP LH <i>see</i>	0.00	0.00	*150.00 F✓
12	1		*FRT REFLECTOR LH <i>see</i>	0.00	0.00	*110.00 F✓
13	1		*FRT PANEL FUSO STICKER X	0.00	0.00	*105.00 FX
14	1		*FRT DOOR LH <i>see</i>	0.00	0.00	*1,050.00 F✓
15	1		*FRT DOOR UPPER HINGE LH ?	0.00	0.00	*75.00 FX
16	1		*FRT DOOR LOWER HINGE LH ?	0.00	0.00	*75.00 FX
17	1		*FRT DOOR CHECKER LH ?	0.00	0.00	*34.00 FX
18	1		*FRT DOOR INNER TRIM BOARD LH ?	0.00	0.00	*280.00 F✓
19	1		*FRT DOOR UPPER ARMEST LH <i>see</i>	0.00	0.00	*250.00 F✓
20	1		*FRT DOOR LOCK LH ?	0.00	0.00	*220.00 FX
21	1		*FRT DOOR RUBBER LH <i>see</i>	0.00	0.00	*190.00 F✓
22	1		*FRT DOOR INNER TRIM SEAL LH ?	0.00	0.00	*125.00 FX
23	1		*FRT DOOR GLASS LH <i>see</i>	0.00	0.00	*265.00 F✓
24	1		*FRT DOOR GLASS INNER MOULDING LH <i>see</i>	0.00	0.00	*70.00 F✓
25	1		*FRT DOOR GLASS OUTER MOULDING LH <i>see</i>	0.00	0.00	*75.00 F✓
26	1		*FRT DOOR GLASS RUN CHANNEL LH ?	0.00	0.00	*120.00 FX
27	1		*FRT DOOR GLASS REGULATOR LH ?	0.00	0.00	*820.00 F✓
28	1		*FRT DOOR GLASS MOTOR LH ?	0.00	0.00	*770.00 F✓
29	1		*FRT DOOR CIGRATTE LIGHTER TRAY LH <i>see</i>	0.00	0.00	*120.00 F✓
30	1		*FRT DOOR GARNISH @FRT LH <i>see</i>	0.00	0.00	*20.00 F✓
31	1		*FRT DOOR GARNISH @RR LH X	0.00	0.00	*26.00 FX
32	1		*FRT STEP GARNISH LH ?	0.00	0.00	*280.00 FX
33	1		*FRT SCUFF PLATE LH ?	0.00	0.00	*90.00 F✓
34	1		*FRT PILLAR INNER LH <i>see</i>	0.00	0.00	*600.00 F✓
35	1		*FRT PILLAR INNER TRIM LH <i>see</i>	0.00	0.00	*80.00 F✓
36	1		*FRT PILLAR OUTER LH <i>see</i>	0.00	0.00	*700.00 F✓
37	1		*FRT WINDSCREEN <i>see</i>	0.00	0.00	*500.00 F✓
38	1		*FRT WINDSCREEN RUBBER <i>see</i>	0.00	0.00	*195.00 F✓
39	1		*FRT INSTRUMENT COVER LH ?	0.00	0.00	*350.00 FX
40	1		*AIRCON BLOWER X	0.00	0.00	*950.00 FX
41	1		*ERP BRACKET <i>see</i>	0	0.00	*26.00 FS
42	1		*HEATER BLOWER X	0.00	0.00	*1,300.00 FX
43	1		*AIRCON COWLING COIL ASSY X	0.00	0.00	*1,600.00 FX
44	1		*FRT PANEL <i>see</i>	0.00	0.00	*1,200.00 F✓

F=Franchise part. S=SpcNett.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Sub Total (S\$)						14,044.00
+ Margin on L,N Items 10.00% (S\$)						1,401.80
Total Parts (S\$)						15,445.80

Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK FRT CABIN RR PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New	1000 1,600.00
2	TO SPRAY PAINTING FRT CORNER PANEL,FRT PANEL,FRT DOOR LH,FRT PILLAR LH, AND AFFECTED AREAS	New	1200 1,500.00
3	TO CHECK WIRING	New	30.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	150 220.00
5	TO TOP UP AIR CON GAS	New	? 100.00
6	TO REMOVE & REFIX UPHOSTERY	New	60 100.00
7	TO REMOVE & REPLACE FRT WINDSCREEN	New	120.00
8	TO REMOVE & REFIX FRT DOOR GLASS	New	60 80.00
9	TO DIAGNOSE & RESET FAULT CODE	New	100 150.00
Gross Labour Cost (S\$)			6370 3,900.00

Sng Ah Tee Motor & Panel Service Pte Ltd/YP2837J/08/12/2022 13:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$121181-
less 20% = \$9694.40
= \$96501-
4/5
Before Exam
\$500
OK? 1/5 Revert.
Shawn
21/4/2023

Ream
Hp 90010068
10 days
4/5
09/12/22 @ 1200
EXCESS: TDA
Revert
Resy after repair

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCGH22004909	Date of Loss:	30/11/2022
Vehicle Reg. No.:	YP2837J	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THERMAL TECH ENGINEERING PTE. LTD.	Contact No:	+6592264051
Driver:	GANESAN SEVAMANI		
Make/Model:	MITSUBISHI FEB21ER3SDEN, 3.0 D (A)	Vehicle Reg. Date:	27/05/2016
Vehicle Colour:	WHITE		
Engine No:	4P10C21813	Chassis No:	FEB21EA20604
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	15,445.80
Miscellaneous Items	0.00
Labour	3,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	19,345.80
+ GST 7.00% (\$\$)	1,354.21
Nett Amount (\$\$)	20,700.01

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System