



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22012290/Upa3q2 Date: 19/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCK 5519U	Veh. Inspected	FBM 6621B
Policy No.	GA345880	Coverage (\$)	0.00
Claim No.	S2M04DO8	Excess (\$)	0.00
Assign From		Assign Date	08/12/2022
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI UH200A	c.c	200
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MLCC91327J0404388	Colour	GREY
Odometer	33266 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/90-13	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-12	DUNLOP	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2022	Inspection Date	09/12/2022
Survey held at	AHM PERFORMANCE BLK 1 KAKI BUKIT AVE 6 #02-46 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	