

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 21/02/2023

Survey Details:

Date of loss	27-Oct-22	
Date of appointment	8-Dec-22	
Date of survey	9-Dec-22	
Location of survey	AHM PERFORMANCE	

Vehicle Details:

Claim Type:	Third pa	arty]
Vehicle number	FBM66	21B	
Make and Model	SUZUKI	SUZUKI UH200A (200cc)	
Date of registration	15/1/2	018	
Excess			
Market Value/ Book Value	\$	11,000.00	(est)
Parf/COE Rebate	\$	3,925.00	(est)
Nett Value/ ERV	\$	7,075.00	(est)

Repair details:

Initial Estimate	\$ 14,450.53

Proposed/Revised repair cost:

Parts	\$ 3,656.70
Check items (estimate)	NIL
Labour	\$ 430.00
Supplementary	NIL
Total	\$ 4,086.70
Lump Sum(if applicable)	\$ 3,200.00

Number of days for repair	<u>4</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

OI INCHED OUT FROM LOT AND COLLIDED WITH TP.		

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 3,200.00	
Loss of use	\$ 120.00	(4DAYS X \$30)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 3,320.00	