

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0331/2022
DATE : 17-NOV-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : TAN LI HUANG (CHEN LIFANG)
ADDRESS : BLK 631 SENJA ROAD
#09-228
S(670631)
TELEPHONE NO : 96161915

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-PC1322J
VEHICLE NO : SMC2740P
MODEL CODE : TDWARDZE12EDAY487Z
MODEL/YEAR : NOTE 1.2 BASE (IV) MY2017
ENGINE NO : HR12295505B
CHASSIS NO : JN1TAAE12Z0980632
MILEAGE : 1 KM
DATE IN : 17/11/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 10/11/2022

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC2740P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2	RSI	R/INSTALL REVERSE SENSOR ASSIST TO REPAIR	55.00	
3	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	95.00	
4	ZZ/001	CONDUCT WHEEL BALANCING & RENEW RH REAR S/RIM	15.00	
5	ZZ/002	REPAIR RR BUMPER & RH REAR FENDER	840.00	
6	ZZ/003	S/PAINT RR BUMPER & RH REAR FENDER	600.00	
TOTAL LABOUR CHARGES			1725.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC2740P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			20.00	
2	ALLOY RIM	40300-0SK92			280.00	
3	CLIP(\$1.4X10)	01553-05933	14.00			
SUB TOTAL			14.00	0.00	300.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			2.80	0.00	0.00	
GRAND TOTAL			11.20	0.00	300.00	
OVERALL TOTAL			311.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMC2740P

TOTAL LABOUR CHARGES 1725.00
TOTAL SPARE PARTS CHARGES 311.20

GRAND TOTAL 2036.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.