

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 23 Dec 2022

**Preliminary Advice**

Insured Vehicle No	: SNE380K	Accident Date	: 06/12/2022
TP Vehicle No	: SJS5867P	Assignment Date	: 08/12/2022
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 5
Date of Inspection	: 08/12/2022		
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,471.40
Revised Amount	:S\$	7,627.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,627.80
 Lump Sum Repair	 :S\$	 6,100.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.