



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012295/Awy3q2 Date: 16/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCX 1888L	Veh. Inspected	SMC 6433A	
Policy No.	D22MTPV01016346	Coverage (\$)	0.00	
Claim No.	CMTD2204380/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	08/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q5 2	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WAUZZZ8R6AA001957	Colour	BLACK	
Odometer	160424 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	PIRELLI	6 mm	
L/H Front Tyre	235/55 R19	PIRELLI	6 mm	
R/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
L/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2022	Inspection Date	12/12/2022	
Survey held at	PROMPT AUTO SOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		