

Adrain : 9689 3735

Prompt Auto Solutions Pte Ltd

8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)

Tel: 97319322 - ROY CHAK

E-mail: promptautosolutions@gmail.com

TP Somp.

Xin Yu.

WAUZZZ8R6AA001957

TO		REPAIR ESTIMATE	
ATTENTION	DATE	JOB TYPE : THIRD PARTY	
VEHICLE DETAILS		ACCIDENT DETAILS	
VEHICLE NO:	SMC6433A	DATE	
MAKE / MODEL:	AUDI Q5	TIME	
CHASSIS NO:	WAUZZZ8R6AA001957		

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	RH front fender <i>Dented</i>	1	\$ 1,286.00	\$ 1,286.00
2	RH front fender splash shield <i>Defend new</i>	1	\$ 241.00	\$ 241.00
3	RH front fender splash shield clips <i>Not in</i>	1set	\$ 80.00	\$ 80.00
4	RH front fender inner enclosure <i>Not in</i>	1	\$ 54.00	\$ 54.00
5	RH front door <i>Distorted</i>	1	\$ 2,850.00	\$ 2,850.00
6	F 1 front door upper outer chrome moulding <i>Not new</i>	1	\$ 256.00	\$ 256.00
7	RH front door lower protector <i>Defend</i>	1	\$ 478.00	\$ 478.00
8	RH front door lower protector clips <i>new</i>	1	\$ 50.00	\$ 50.00
9	RH front door outer handle <i>Not in</i>	1	\$ 721.00	\$ 721.00
10	RH front door outer handle side cover <i>Not in</i>	1	\$ 33.00	\$ 33.00
11	RH front door weatherstrip <i>New</i>	1	\$ 228.00	\$ 228.00
12	RH front door lock <i>Damaged</i>	1	\$ 585.00	\$ 585.00
13	RH front door lock catch <i>Not new</i>	1	\$ 123.00	\$ 123.00
14	RH front door inner trim board <i>Defend</i>	1	\$ 1,532.00	\$ 1,532.00
15	RH front door inner trim board clips <i>new</i>	1set	\$ 70.00	\$ 70.00
16	RH front door glass regulator gear <i>Damaged</i>	1	\$ 299.00	\$ 299.00
17	RH front door glass regulator gear motor <i>Not new</i>	1	\$ 452.00	\$ 452.00
18	RH front door speaker <i>Defend Not in</i>	1	\$ 287.00	\$ 287.00
19	RH front door upper hinge <i>Defend Not in</i>	1	\$ 98.00	\$ 98.00
20	RH front door lower hinge <i>Defend</i>	1	\$ 98.00	\$ 98.00
21	RH front door checker <i>Not new</i>	1	\$ 153.00	\$ 153.00
22	RH front door pillar <i>Repair</i>	1	\$ 1,293.00	\$ 1,293.00
23	RH side door centre pillar <i>Dented</i>	1	\$ 2,008.00	\$ 2,008.00
24	RH side door centre pillar inner lower garnish <i>Not new</i>	1	\$ 239.00	\$ 239.00
25	RH rear door <i>Distorted</i>	1	\$ 2,894.00	\$ 2,894.00
26	RH rear door upper outer chrome moulding <i>Not new</i>	1	\$ 256.00	\$ 256.00
27	RH rear door lower protector <i>Defend</i>	1	\$ 467.00	\$ 467.00
28	RH rear door lower protector clips <i>new</i>	1	\$ 50.00	\$ 50.00
29	RH rear door outer handle <i>Not in</i>	1	\$ 721.00	\$ 721.00
30	RH rear door outer handle side cover <i>Not in</i>	1	\$ 33.00	\$ 33.00
31	RH rear door weatherstrip <i>New</i>	1	\$ 228.00	\$ 228.00
32	RH rear door lock <i>Damaged</i>	1	\$ 585.00	\$ 585.00
33	RH rear door lock catch <i>Not new</i>	1	\$ 123.00	\$ 123.00
34	RH rear door inner trim board <i>Defend</i>	1	\$ 1,532.00	\$ 1,532.00
35	RH rear door inner trim board clips <i>new</i>	1set	\$ 70.00	\$ 70.00
36	RH rear door glass regulator gear <i>Defend</i>	1	\$ 299.00	\$ 299.00
37	RH rear door glass regulator gear motor <i>Not new</i>	1	\$ 452.00	\$ 452.00
38	RH rear door speaker <i>Defend</i>	1	\$ 287.00	\$ 287.00
39	RH rear door upper hinge <i>Not in</i>	1	\$ 98.00	\$ 98.00
40	RH rear door lower hinge <i>Defend</i>	1	\$ 98.00	\$ 98.00
41	RH rear door checker <i>Not in</i>	1	\$ 153.00	\$ 153.00
	Rear RH Fender Inner shield <i>Defend</i>	1	\$ 197	\$ 197

Front Door Pillar Inner Garnish

201 *Defend*

Rear RH Wheel Rim 450 ✓

Door Slep Panel Garnish x02 160x2=320 ✓
Defend

TOTAL PRICE: \$ 21,860.00
LIST LESS 5%: \$ 1,093.00
SUB TOTAL PRICE: \$ 20,767.00

980.

1290.

1800

1290

15749

ben 10%: 14174.10

S/N	DESCRIPTIONS	QTY	UNIT S/N PRICE	TOTAL S/N PRICE

S/N TOTAL PRICE: \$

S/N	DESCRIPTIONS	PRICE
1	Labour charges on affected areas and replaced parts as listed	\$ 2,000.00 1400
2	Re-spray affected areas and parts	\$ 1,800.00 1300
3	Check wiring and lighting system	\$ 120.00 30
4	Apply anti rust chemical coating	\$ 100.00 80
5	Remove and replace RH front door inner mechanism to new door	\$ 300.00 80
6	Remove and replace RH rear door inner mechanism to new door	\$ 300.00 80
7	Remove and reinstall dashboard and all attachments to assist repair	\$ 500.00 X
8	Remove and reinstall LH side door centre pillar inner garnish and trims to assist repair	\$ 500.00 200
9	Reset control unit and fault codes	\$ 480.00 100
LABOUR TOTAL PRICE: \$		6,100.00

ESTIMATE REPORT

TOTAL PARTS PRICE	\$ 20,767.00
TOTAL LABOUR PRICE	\$ 6,100.00
TOTAL AMOUNT	\$ 26,867.00

3520

APPROVED DETAILS

NO. OF REPAIR DAYS :
P & P OR LUMP SUM :
SURVEYED BY :
CONTACT NUMBER :
E-MAIL :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

14/12/22

2/s . 12 Days.

1/s : 14.11c.