

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Lee

Date: 12 May 2023

**Preliminary Advice**

Insured Vehicle No	: GBJ9867E	Accident Date	: 05/12/2022
TP Vehicle No	: SLR101E	Assignment Date	: 08/12/2022
Make	: MERCEDES-BENZ E200	Est. Duration of Repair	: 8
Date of Inspection	: 09/12/2022		
Inspection At	: AUTOSPRINT PTE LTD (HQ) 24, LENG KEE ROAD, #07-01/02 LENG KEE AUTOPOINT SINGAPORE 159096		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,399.60
Revised Amount	:S\$	15,385.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,385.60

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.