

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
Ad hoc					
1	Rear Boot Cover	1.00		2,000.00	2,000.00
2	Rear Boot Rubber	1.00		240.00	240.00
3	Rear Boot Moulding	1.00		160.00	160.00
4	Rear Boot Inner Lock	1.00		280.00	280.00
5	Rear Boot Cover Star Emblem	1.00		56.00	56.00
6	Rear Boot Cover E300 Emblem	1.00		112.00	112.00
7	Rear Boot Cover Hinges	2.00		90.00	180.00
8	Rear Boot Surrounding Garnish	1.00		256.00	256.00
9	Rear Boot Cover Inner Trim	1.00		560.00	560.00
10	Rear Bumper	1.00		1,680.00	1,680.00
11	Rear Bumper Lower	1.00		304.00	304.00
12	Rear Bumper Reinforcement	1.00		720.00	720.00
13	Rear Bumper Reflectors	2.00		48.00	96.00
14	Rear Bumper Sensors	2.00		169.00	338.00
15	Rear Bumper Rivets	1.00		120.00	120.00
16	Rear Tail Lamps	2.00		720.00	1,440.00
17	Rear Tail Lamp Brackets	2.00		80.00	160.00
18	Rear Exhaust Chrome Rims	2.00		160.00	320.00
19	Labour Charge to straighten & align rear lower end panel, remove & replace the above listed damaged parts	1.00		2,200.00	2,200.00
20	Labour Charge to reconnect rear lamp wire harness, coding & reprogramming systems	1.00		450.00	450.00
21	Labour Charge to remove & reinstall rear boot inner trimmings & attachment to facilitate repair works	1.00		120.00	120.00
22	Labour Charge to putty & respray painting same (5 portions)	1.00		2,000.00	2,000.00

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: 13,792.00
GST 7.0% : 965.44
Total Amount: 14,757.44