

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (\$)	Amt (\$)
Ad hoc					
1	Rear Boot Cover <i>4/</i>	1.00		2,000.00	2,000.00 ✓
2	Rear Boot Rubber <i>u/</i>	1.00		240.00	240.00 ✓
3	Rear Boot Moulding <i>cn/</i>	1.00		160.00	160.00 ✓
4	Rear Boot Inner Lock <i>cut/</i>	1.00		280.00	280.00 ✓
5	Rear Boot Cover Star Emblem <i>u/</i>	1.00		56.00	56.00 ✓
6	Rear Boot Cover E300 Emblem <i>u/</i>	1.00		112.00	112.00 ✓
7	Rear Boot Inner Hinge Covers <i>? cut/</i>	2.00	8558	90.00	180.00 ✓
8	Rear Boot Surrounding Garnish <i>x 11</i>	1.00		256.00	256.00 X
9	Rear Boot Cover Inner Trim <i>? de/</i>	1.00		560.00	560.00 ✓
10	Rear Bumper <i>de/</i>	1.00		1,680.00	1,680.00 ✓
11	Rear Bumper Lower <i>sur/</i>	1.00		304.00	304.00 ✓
12	Rear Bumper Reinforcement <i>? H/</i>	1.00		720.00	720.00 ✓
13	Rear Bumper Reflectors <i>LH-7/RH-5/</i>	2.00		48.00	96.00 X
14	Rear Bumper Sensors <i>dis/</i>	2.00		169.00	338.00 ✓
15	Rear Bumper Rivets <i>u/</i>	1.00		120.00	120.00 ✓
16	Rear Tail Lamps <i>cn/</i>	2.00		720.00	1,440.00 ✓
17	Rear Tail Lamp Brackets <i>? cn/</i>	2.00		80.00	160.00 ✓
18	Rear Exhaust Chrome Rims <i>? RH sur/</i>	2.00		160.00	320.00 X
19	Labour Charge to straighten & align rear lower end panel, remove & replace the above listed damaged parts <i>ex 400</i>	1.00		2,200.00	2,200.00 <i>720</i>
20	Labour Charge to reconnect rear lamp wire harness, coding & reprogramming systems <i>Labour 3660</i>	1.00		450.00	450.00 <i>200</i>
21	Labour Charge to remove & reinstall rear boot inner trimmings & attachment to facilitate repair works <i>ex 400</i>	1.00		120.00	120.00 <i>60</i>
22	Labour Charge to putty & respray painting same (5 portions)	1.00		2,000.00 <i>1800</i>	2,000.00 <i>600</i>
23	Rear Boot Cover Hinges <i>? cut/</i>	2.00		248.00	496.00 <i>720</i>
24	Rear Boot Cover Rubber Stopper <i>u/</i>	2.00	528	16.00	32.00 ✓
25	Rear End Lower Panel <i>? repair</i>	1.00		1,440.00	1,440.00 X

Continue on next page...

QUOTATION

To: **Chris Tong**
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : **Chris Tong (86666998)**

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
-----	-------------	-----	-----	-----------	-----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 9001368

8 days

P/P

09/12/22 @ 1050

Resurvey before paint

email: rasul@lkkauto.com

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: 15,760.00
GST 7.0% : 1,103.20
Total Amount: 16,863.20

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
26	Rear Boot Auto Opening Motor (Supplementary) short ✓	1.00		880.00	880.00 —
27	Rear Boot Cover Lower Inner Lock Assy. (Supplementary) cut ✓	1.00		400.00	400.00 —
28	Rear Boot Centre Inner Plastic Trim (Supplementary) cr ✓	1.00		416.00	416.00 —
29	Rear Bumper Inner Top Plastic Beam (supplementary) cr ✓	1.00		136.00	136.00 —
30	Rear Bumper Mountings (supplementary) cr ✓	2.00		67.00	134.00 —
31	Rear Boot Lower Lock Motor (supplementary) short ✓	1.00		160.00	160.00 —
32	Rear Boot Inner Control Unit (supplementary) short ✓	1.00		480.00	480.00 —
33	Rear Boot Inner Carpet Retaining Clips (supplementary) new ✓	1.00		24.00	24.00 —
34	Rear Boot Inner Control Fuse (supplementary) short ✓	1.00		9.60	9.60 —

Spare Part → 11725.60 ✓
Lab & Paint → 3660.00 + +
→ 15385.60 +
Add S/L 441 → 1230.84 + +
Final Amt → 16,616.44 +

8558.00
528.00
2639.60
11725.60
3660.00
15385.60
54 GST
16616.44

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: 18,399.60
GST 7.0% : 1,287.97
Total Amount: 19,687.57

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
-----	-------------	-----	-----	-----------	-----------

Rasul
Hp 9001268
7 X 8 days + 1 day = 8 day
P/P
09/12/22 @ 1050
Rasul before print
email: rasul@1kkauto.com

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: 15,760.00
GST 7.0% : 1,103.20
Total Amount: 16,863.20