

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLR7149Y

Make & Model: Mitsubishi Attrage

Chassis number: MMBSTA13AHH005494

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	✓ 858.00
2	Bootlid centre emblem	1	✓ 53.00
3	Bootlid "Attrage" emblem	1	✓ 21.00
4	Bootlid "MIVEC" emblem	1	✓ 43.00
5	Bootlid chrome moulding	1	✓ 318.00
6	Bootlid chrome moulding clips	1set	50.00
7	Bootlid RH hinge	1	192.00
8	Bootlid LH hinge	1	192.00
9	Bootlid lock	1	✓ 208.00
10	Bootlid lock catch	1	68.00
11	Bootlid weatherstrip	1	178.00
12	Rear bumper	1	✓ 654.00
13	Rear bumper clips	1set	60.00
14	Rear bumper RH retainer	1	32.00
15	Rear bumper LH retainer	1	✓ 32.00
16	Rear bumper LH reflector	1	41.00
17	Rear bumper RH reflector	1	41.00
18	LH taillamp assy	1	✓ 402.00
19	LH taillamp panel	1	98.00
20	LH taillamp lock clips	1set	22.00
21	RH taillamp assy	1	✓ 402.00
22	RH taillamp panel	1	98.00
23	RH taillamp lock clips	1set	22.00
24	End panel	1	✓ 455.00
25	End panel inner garnish	1	✓ 89.00
26	End panel inner garnish clips	1set	60.00
27	End panel air vent	1	39.00
28	End panel air vent cover	1	53.00
29	End panel RH side cover	1	28.00
30	End panel antenna sensor	1	101.00
31	End panel buzzer sensor	1	✓ 95.00
32	LH rear fender	1	✓ 808.00
33	LH rear fender inner trim board	1	✓ 233.00
34	LH rear fender inner trim board clips	1set	45.00
35	LH rear fender splash shield	1	55.00
36	LH rear fender splash shield clips	1set	30.00
37	RH rear fender	1	808.00
38	RH rear fender inner trim board	1	233.00
39	RH rear fender inner trim board clips	1set	45.00

40	RH rear fender splash shield	1	\$	55.00
41	RH rear fender splash shield clips	1set	\$	30.00
42	Spare tyre panel	1	\$	923.00
43	Spare tyre panel mat	1	\$	198.00
44	Spare tyre panel top cover	1	\$	339.00
45	Spare tyre panel insulator	1	\$	187.00
46	Exhaust silencer	1	\$	598.00
47	Exhaust silencer gasket	1	\$	36.00
48	Exhaust silencer hangers	1	\$	87.00

\$ 9,695.00
 Parts less 10% \$ 969.50
 Total \$ 8,725.50

4933
 -10%
 4439.70

No.	Special Nett Items		Amount S\$
1	Bootlid "C&C" emblem	1	\$ 85.00
2	Bootlid seal	1	\$ 60.00
3	End panel joint sealant	1	\$ 70.00
4	Spare tyre panel joint sealant	1	\$ 80.00
5	Rear bumper reverse sensor	1set	\$ 320.00
6	Rear reverse camera	1	\$ 780.00
7	Rear number plate	1	\$ 70.00
8	Rear windscreen glass sealant	1	\$ 70.00
9	Rear windscreen glass inner seal	1	\$ 50.00
10	RH taillamp panel joint sealant	1	\$ 40.00
11	LH taillamp panel joint sealant	1	\$ 40.00

Total: \$ 1,665.00

325

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,400.00
2	Spray painting on affected areas and panels	\$ 2,000.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 100.00
5	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00
6	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 350.00
7	Remove and replace exhaust silencer and hangers to assist repair	\$ 180.00

8	Remove and replace rear reverse camera to assist repair	\$ 120.00	X
9	Remove and reinstall roof lining, seats and carpet to assist repair	\$ 480.00	X
10	Mount vehicle on chassis alignment bench to repair chassis frames	\$ 650.00	X
11	Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair	\$ 220.00	X

Total: \$ 6,700.00

1550

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 8,725.50

Special Nett: \$ 1,665.00

Labour: \$ 6,700.00

Total Amount: \$ 17,090.50

6314.70

L/S - 5051.76
= 5050

Tanfer 9749 5749
WP 9/12/22 @ 445
c/s resurvey after repair
tanfer @ 11 hours - 6 days

- To check consistency of accident
- To check part prices

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer