

ASS. REC. BY:

REF:

C72 / 22 012302 / Kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B.I. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1. Unable to locate Ind part, repair on I.B.I. basis.

Veh No:

SLN 37426 Yr Regn: 04.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

3

c.c

1886

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

231266

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MM 6DL2SAAGW 197038

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

7070

R:

185/60R16

R:

7070

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TOYO

Front

Rear

R/Bal.

4

mm

R/Bal.

7

mm

L/Bal.

4

mm

L/Bal.

7

mm

D.O.A.

6/12/22

D.O.I.

9/12/2022

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The vehicle had commenced its repair work

The UIC / Chassis frame / Body Structure affected due to collision.

at the time of inspection.

Date/Time, File Pass to?



Prell. Report



Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. SI

Fees

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-SMA 8783L
Repairer Reference: 73223
Date calculated: 08/12/2022 11:31 AM

Full Report
Registration: SLN 3742G
Printed: 08/12/2022 11:31 AM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-SMA 8783L	Date of Incident:	06/12/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	MAZDA (Mazda [36])		
Model:	2 SEDAN 1.5L SP 6E (3 - BK Model from 06/2003 to 02/2009 [38]/3)		
Sub Model:			
Model Sheet Number:	36 38 01		
Registration:	SLN 3742G		
VIN number:			
Odometer:	231266		
Model Specs			
4-DOOR	AIR CONDITIONING	FOG LAMPS	1.6 LTR 77/79KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

*Not Authorised
Repair By
5 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NN	RENEW REAR PANEL CPL INCLUDES: R + R BUMPER, TAILLAMPS, BOOT SEAL AND ALL TRIMS IN THE REPAIR SECTION		56.0	235.20
NN	R + R REAR BUMPER INCLUDES: R + R TAILLAMPS		5.0	21.00
NN	RENEW REAR BUMPER (REMOVED)		2.0	8.40
NN	R + R REAR END PANEL TRIM		2.0	8.40
NN	R + R BOOTLID SEAL		3.0	12.60
NN	RENEW BOOTLID INCLUDES: R + R BOOTLID, STRAIGHTEN AND ADJUST BOOTLID, CONVERT ATTACHED PARTS		8.0	33.60
3482	R/RR SIDE PANEL REPAIR		10 20.0* ✓	84.00
3901	BOOTFLOOR REPAIR		30 50.0* ✓	210.00
4183	L/R COVER PANEL REPAIR		10.0* ✓	42.00
4184	R/R COVER PANEL REPAIR		10.0* ✓	42.00

Labour Cost
Panel / Mechanical Labour

Total of Labour

Hrs	WU	
16.60	166.0	697.20
		697.20

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR PANEL CPL NEW PART PAINTING	22.0	
	BOOTLID/TAILGATE NEW PART PAINTING	15.0	
	REAR BUMPER NEW PART PAINT K1R	12.0	
	R/RR SIDE PANEL REPAIR PAINTING <50%	15.0	
	L/RR SIDE PANEL SURFACE PAINT	7.0	
	BOOTFLOOR SURFACE PAINT	10.0	
	L/R COVER PANEL SURFACE PAINT	4.0	
	R/R COVER PANEL SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL CPL NEW PART PAINTING	27.50
2931	BOOTLID/TAILGATE NEW PART PAINTING	42.83
2581	REAR BUMPER NEW PART PAINT K1R	55.60
3482	R/RR SIDE PANEL REPAIR PAINTING <50%	24.55
3481	L/RR SIDE PANEL SURFACE PAINT	18.92
3901	BOOTFLOOR SURFACE PAINT	30.63
4183	L/R COVER PANEL SURFACE PAINT	1.25
4184	R/R COVER PANEL SURFACE PAINT	1.25

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint	42.00 SGD/h		
Preparation Main Work Metal	2.50	89.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	11.90	499.80

Material Cost - Paint

	Price SGD
New Part Painting	70.33
New Part Painting - Plastic K1R	55.60
Repair Painting	24.55
Surface-/Blend Paint	52.05
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	240.13

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
3015	BADGE MAZDA		Original	✓	35.00
3023	BADGE MAZDA		Original	✓	35.00

Code	Description	Part Number	Part Source	Price SGD
2931	BOOTLID/TAILGATE		Original	✓ 440.00
2977	BOOTLID LOCK		Original	✓ 100.00
2944	BOOTLID SEAL		Original	✓ 70.00
2614	R/R BUMPER REFLECTOR		Original	✓ 25.00
3288	R/R OUTER LAMP		Original	✓ 180.00
1001	REAR ANTENNA	RENEW	Original	✓ 100.00
	SENSOR			
2581	REAR BUMPER		Original	✓ 480.00
2711	REAR PANEL CPL		Original	✓ 250.00
4985	REAR PANEL TRIM		Original	✓ 40.00
f: OEM Parts				0.00
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				1,755.00
Fixed Sundry Parts Price				100.00
Total				1,855.00

Extras

Code	Description	Price SGD
1000	REV SENSOR +INSTALL	✓ 200.00*
Total Extras		200.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	1,755.00	
Total Parts	100.00	1,855.00
Labour Time Base 10 WU/h		
Total 166.0 WU X 42.00 SGD/h	697.20	
Total of Labour		697.20
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 119.0 WU X 42.00 SGD/h	499.80	
Material Cost	240.13	
Total Paint Including Material		739.93
Repair Cost Excludes GST		3,492.13
GST (+7.0%)		244.45
Repair Cost Included GST		3,736.58

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/12/2022 15:58 (SGT)
Reported by Both
Date of Accident 06/12/2022 09:00 (SGT)
Exact Location of Accident Simei Ave, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLN3742G

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner A N S Plumbing & Sanitary Pte Ltd
Company Reg No 1XXXXX588C
Email Address yeosteven@anspns.com.sg
Mobile Phone No (Phone) +65-93372225
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mazda
Model 2
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number 22-MU005635-R05

DRIVER

Name of Driver Yeo Siew Beng
NRIC No SXXXX423C
Date Of Birth 13/12/1967
Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

- 6 DEC 2022

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

- 6 DEC 2022

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



SIMEI AVENUE

A - SLN 3742G

B - SMA 8783L

C - SBT 19004

D - SMD 4856X