



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22007111/Rny3e2-1 Date: 19/12/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4109A	Veh. Inspected	GV 5411R	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/026065	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	08/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35YX0K210547	Colour	WHITE	
Odometer	113128 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	7 mm	
L/H Front Tyre	195 R15C	MICHELIN	7 mm	
R/H Rear Tyre	155 R12C (D)	LINAM	5/5 mm	
L/H Rear Tyre	155 R12C (D)	LINAM	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/07/2022	Inspection Date	27/07/2022	
Survey held at	SHENG KHOON MOTOR SERVICE 393 WOODLANDS ROAD BLK D4 YEE TEE INDUSTRIAL ESTATE SINGAPORE 677972			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	