



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0370722

Date of Report : 26/08/2022

To : M/s. Alvas Dairy Pte Ltd
C/o. Blk D4 Woodlands Road
393 Yew Tee Ind. Estate
Singapore 677972

Date of Assignment : 27/07/2022
Report requested by : M/s. Alvas Dairy Pte Ltd
Date of Accident : 21/07/2022
Date of Inspection : 27/07/2022
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : GV5411R
Make & Model : Toyota Dyna (Refrigerated Vehicle)
Date of Registration : 16/07/2018
Colour : White

Engine Capacity (cc) : 2982
Mileage (km) : 113128km
Chassis / Frame No. : JTFAT35YX0K210547
Engine No. : 1KD2800550

TYRE CONDITION

Front LH : 5 mm
Make : Michelin

Front RH : 5 mm
Make : Michelin

Rear LH : 4 mm / 4 mm
Make : Falken

Rear RH : 4 mm / 4 mm
Make : Falken

Road wheels Type : Standard

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Sheng Khoon Motor Service
Blk D4 Woodlands Road, 393, Yew Tee Ind. Estate, Singapore 677972

ASSESSMENT

Repairer's Estimate : \$ 4,900.00
Revised Amount : \$ 3,600.00
Less Excess : \$ -
Recommended Reserve : \$ 2,880.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GV5411R

Report No. : PAS/TP/0370722

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Sheng Khoon Motor Service, Blk D4 Woodlands Road, 393, Yew Tee Ind. Estate, Singapore 677972.

POINT OF IMPACT

At the LHR portion.

DAMAGES

The rear refrigerated box LH side panel and rear door aluminium support frame were Dented/Cracked.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$3,600.00.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$2,880.00.

This inspection was conducted entirely on a '**Without Prejudice**' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd



Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GV5411R

Report No. : PAS/TP/0370722

APPRAISEMENT SCHEDULE

S/No.	Parts/Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove, replace, realign refrigerated box LH side panel and rear door aluminium support frame. (Include supply refrigerated box LH side panel, rear door aluminium support frame and sealants)	\$ 2,500.00	\$ 1,800.00
2	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 800.00
3	To supply body sticker (Advertisement Graphics) film materials and wrap, apply on refrigerated box LH side panel.	\$ 1,200.00	\$ 1,000.00
Labour Total :		<u>\$ 4,900.00</u>	<u>\$ 3,600.00</u>
Total (Parts & Labour) :		<u>\$ 4,900.00</u>	<u>\$ 3,600.00</u>

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 2,880.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **7 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

18 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.