

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1111/2022/EQ
DATE : 12-Dec-22
WIP : 54217

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/12/2022

YOUR INSURED VEH NO : ET 1100 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SIM SWEE PIN
ADDRESS : 606 CHO A CHU KANG STREET 62
#08-139
SINGAPORE 680606
TELEPHONE : HP +65 91446396
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070005881-02
VEHICLE NO : **SMR 521 P**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 16/11/2017
ENGINE NO : CVN 040544
CHASSIS NO : WAUZZZF49HA177371
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Dec-22
PLACE OF ACCIDENT : MULTI STOREY CAR PARK AT ST 62

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 521 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 521 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
4	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
8	FRONT BUMPER TOP COVER	1	\$ 143.00	
9	CAUTION SIGN STICKER	1	\$ 16.00	
10	AIR CONDITIONER STICKER	1	\$ 9.00	
11	FRONT FENDER - RH	1	\$ 861.00	
12	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00	
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	
14	FRONT FENDER BRACKET - RH	1	\$ 41.00	
15	FRONT FENDER RIVET	7	\$ 27.00	
16	FRONT FENDER BRACE - RH	1	\$ 132.00	
17	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00	
18	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	
19	FRONT WHEEL SPOILER	1	\$ 82.00	
20	FRONT WHEEL SPOILER END PLATE - RH	1	\$ 40.00	
SUB TOTAL SPARE PARTS		:	\$ 5,560.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 521 P**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL SPOILER STONE CHIP GUARD	1	\$ 57.00	
22	FRONT FENDER LEDGE COVER - RH LONG	1	\$ 35.00	
23	FRONT FENDER LEDGE COVER - RH SHORT	1	\$ 26.00	
24	HEADLIGHT - RH	1	\$ 8,294.00	
25	LIFT CYLINDER - RH	1	\$ 231.00	
26	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
27	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 14,710.00	
TOTAL LABOUR CHARGES		:	\$ 5,002.00	
GRAND TOTAL		:	\$ 19,712.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT