

ASS. REC BY: Tough

REF:

116

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 100

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 995K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Keer Sany

Vehicle: IN / OUT

Veh No: SSR 32145 Yr Regn: 2018, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Indi 143 SB C.C. 999

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 29/74 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WA4 ZZZ 8V8 JA/15083

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 8/12/22

Survey held at Premium ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.A. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

☐ S + RS. ☐ SI

Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01092/2022/EQ
DATE : 7-Dec-22
WIP : 53547

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : DR SUYUN TANG
ADDRESS : BLK 107A EDGEFIELD PLAINS
#17-108
SINGAPORE 821107
TELEPHONE : HP +65 81003579
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800069536-04
VEHICLE NO : **SJR 3214 S**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 14/6/2018
ENGINE NO : CHZ 464327
CHASSIS NO : WAUZZZ8V8JA115083
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : B2 CARPARK VIVO CITY


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJR 3214 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	✓
2	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	? photo.
3	TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR LOWER SECTION FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	2000 ✓
4	TO RESPRAY LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR AND DOOR ENTRANCE. ✓ ✓ ✓	\$ 3,500.00	1925
5	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,462.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJR 3214 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR SIDE PANEL - LH	1	\$ 4,445.00	bt ✓
2	REAR WHEEL SPOILER - LH	1	\$ 39.00	?
3	REAR WHEEL HOUSING LINER	1	\$ 260.00	?
4	REAR DOOR - LH	1	\$ 2,973.00	bt ✓
5	REAR OUTER DOOR SEAL - LH	1	\$ 179.00	ner ✓
6	BONDING AGENT	1	\$ 51.00	?
7	CLEANING SOLUTION	1	\$ 74.00	?
8	APPLICATOR	1	\$ 9.00	?
9	REAR DOOR CATCH - LH	1	\$ 105.00	?
10	REAR DOOR INNER SEAL - LH	1	\$ 213.00	X
11	REAR WINDOW REGULATOR - LH	1	\$ 286.00	?
12	REAR ALUMINIUM RIM	1	\$ 1,303.00	cut ✓
13	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	ner ✓
14	STONE CHIP	S/N	\$ 180.00	ner ✓
15	ACRYLIC SEALANT	S/N	\$ 180.00	ner ✓
16	CAVITY WAX	S/N	\$ 140.00	ner ✓
17	METAL FILLER POWDER	S/N	\$ 280.00	ner ✓
18	LHS REAR TYRE	S/N	TBC ?	
19	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS			\$ 11,121.00	
TOTAL LABOUR CHARGES			\$ 9,462.00	
GRAND TOTAL			\$ 20,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 97495749
Not Authorise 2/12/22 C 1030m
EX: to be advise
Resurvey before paint
12 days
Taufik C 1030m

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT